DxDiag

System Information

Time of this report: 4/17/2021, 00:14:18
Machine name: DEX2
Machine Id: {47D74B11-6131-4556-8643-120B24754BEC}
Operating System: Windows 10 Home 64-bit (10.0, Build 19042) (19041.vb_release.191206-1406)
Language: German (Regional Setting: German)
System Manufacturer: HP
System Model: HP Laptop 17-by3xxx
BIOS: F.09 (type: UEFI)
Processor: Intel(R) Core(TM) i7-1065G7 CPU @ 1.30GHz (8 CPUs), ~1.5GHz
Memory: 16384MB RAM
Available OS Memory: 16072MB RAM
Page File: 8959MB used, 55113MB available
Windows Dir: C:\windows
DirectX Version: DirectX 12
DX Setup Parameters: Not found
User DPI Setting: 110 DPI (114 percent)
System DPI Setting: 144 DPI (150 percent)
DWM DPI Scaling: Enabled
Miracast: Available, with HDCP
Microsoft Graphics Hybrid: Supported
DirectX Database Version: 1.2.1
DxDiag Version: 10.00.19041.0928 64bit Unicode

DxDiag Notes

Display Tab 1: No problems found.
Display Tab 2: No problems found.
Sound Tab 1: No problems found.
Sound Tab 2: No problems found.
Input Tab: No problems found.

DirectX Debug Levels

Direct3D: 0/4 (retail)
DirectDraw: 0/4 (retail)
DirectInput: 0/5 (retail)
DirectMusic: 0/5 (retail)
DirectPlay: 0/9 (retail)
DirectSound: 0/5 (retail)
DirectShow: 0/6 (retail)

Display Devices

Card name: Intel(R) Iris(R) Plus Graphics
Manufacturer: Intel Corporation
Chip type: Intel(R) Iris(R) Graphics Family
DAC type: Internal
Device Type: Full Device (POST)
Device Key: Enum\PCI\VEN_8086&DEV_8A52&SUBSYS_868F103C&REV_07
Device Status: 0180200A [DN_DRIVER_LOADED|DN_STARTED|DN_DISABLEABLE|
DN_NT_ENUMERATOR|DN_NT_DRIVER]
Device Problem Code: No Problem
Driver Problem Code: Unknown
Display Memory: 8164 MB
Dedicated Memory: 128 MB
Shared Memory: 8036 MB
Current Mode: 1920 x 1080 (32 bit) (60Hz)
HDR Support: Not Supported
Display Topology: External
Display Color Space: DXGI_COLOR_SPACE_RGB_FULL_G22_NONE_P709
Color Primaries: Red(0.639648,0.330078), Green(0.299805,0.599609),
Blue(0.150391,0.059570), White Point(0.312500,0.329102)
Display Luminance: Min Luminance = 0.500000, Max Luminance = 270.000000,
MaxFullFrameLuminance = 270.000000
Monitor Name: Generic PnP Monitor
Monitor Model: LG PROJECTOR
Monitor Id: GSM0001
Native Mode: 1920 x 1080(p) (60.000Hz)
Output Type: HDMI
Monitor Capabilities: HDR Not Supported
Display Pixel Format: DISPLAYCONFIG_PIXELFORMAT_32BPP
Advanced Color: Not Supported
Driver Name: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\igdumdim64.dll,C:\windows\System32\DriverStore\
FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igd10iumd64.dll,C:\windows\System32\
DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igd10iumd64.dll,C:\windows\
System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igd12umd64.dll
Driver File Version: 27.20.0100.8853 (English)
Driver Version: 27.20.100.8853
DDI Version: 12
Feature Levels: 12_1,12_0,11_1,11_0,10_1,10_0,9_3,9_2,9_1
Driver Model: WDDM 2.7
Hardware Scheduling: Supported:False Enabled:False
Graphics Preemption: Triangle
Compute Preemption: Thread
Miracast: Not Supported by Graphics driver
Detachable GPU: No
Hybrid Graphics GPU: Integrated
Power P-states: Not Supported
Virtualization: Paravirtualization
Block List: DISABLE_HWSCH
Catalog Attributes: Universal:False Declarative:True
Driver Attributes: Final Retail
Driver Date/Size: 14.10.2020 02:00:00, 1471144 bytes
WHQL Logo'd: Yes

WHQL Date Stamp: Unknown
Device Identifier: {D7B78E66-C912-11CF-1951-EBA6BCC2D635}
Vendor ID: 0x8086
Device ID: 0x8A52
SubSys ID: 0x868F103C
Revision ID: 0x0007
Driver Strong Name: oem117.inf:5f63e53448217367:iICLD_w10_DS_N:27.20.100.8853:PCI\VEN_8086&DEV_8A52&SUBSYS_868F103C
Rank Of Driver: 00CF0001
Video Accel: ModeMPEG2_A ModeMPEG2_C ModeWMV9_C ModeVC1_C
DXVA2 Modes: DXVA2_ModeMPEG2_VLD DXVA2_ModeMPEG2_IDCT DXVA2_ModeVC1_D2010 {E07EC519-E651-4CD6-AC84-1370CCEEC851} {BCC5DB6D-A2B6-4AF0-ACE4-ADB1F787BC89} DXVA2_ModeWMV9_IDCT DXVA2_ModeVC1_IDCT DXVA2_ModeH264_VLD_NoFGT DXVA2_ModeH264_VLD_Stereo_Progressive_NoFGT DXVA2_ModeH264_VLD_Stereo_NoFGT DXVA2_ModeH264_VLD_Multiview_NoFGT {C528916C-C0AF-4645-8CB2-372B6D4ADC2A} {91CD2D6E-897B-4FA1-B0D7-51DC88010E0A} DXVA2_ModeVP8_VLD {442B942A-B4D9-4940-BC45-A882E5F919F3} {97688186-56A8-4094-B543-FC9DAAA49F4B} {1424D4DC-7CF5-4BB1-9CD7-B63717A72A6B} {C346E8A3-CBED-4D27-87CC-A70EB4DC8C27} {FFC79924-5EAF-4666-A736-06190F281443} {464BDB3C-91C4-4E9B-896F-225496AC4ED6} {9B31316B-F204-455D-8A8C-9345DCA77C01} {AFE4285C-AB63-4B2D-8278-E6BAACEA2CE9} {277DE9C5-ED83-48DD-AB8F-AC2D24B22943} {04C5BA10-4E9A-4B8E-8DBF-4F4B48AFA27C} {0ACEF8BC-285F-415D-AB22-7BF2527A3D2E} {24D19FCA-C5A2-4B8E-9F93-F8F6EF15C890} {353ACA91-D945-4C13-AE7E-469060FAC8D8} {28566328-F041-4466-8B14-8F5831E78F8B} {6B4A94DB-54FE-4AE1-9BE4-7A7DAD004600} {B8B28E0C-ECAB-4217-8C82-EAAA9755AAF0} {8732ECFD-9747-4897-B42A-E534F9FF2B7A} {E139B5CA-47B2-40E1-AF1C-AD71A67A1836} {056A6E36-F3A8-4D00-9663-7E9430358BF9} {5415A68C-231E-46F4-878B-5E9A22E967E9} {161BE912-44C2-49C0-B61E-D946852B32A1} {580DA148-E4BF-49B1-943B-4214AB05A6FF} {CEE393AB-1030-4F7B-8DBC-55629C72F17E} {87B2AE39-C9A5-4C53-86B8-A52D7EDBA488} {10E19AC8-BF39-4443-BEC3-1B0CBFE4C7AA} {8C56EB1E-2B47-466F-8D33-7DBCD63F3DF2} DXVA2_ModeHEVC_VLD_Main {75FC75F7-C589-4A07-A25B-72E03B0383B3} DXVA2_ModeHEVC_VLD_Main10 {E484DCB8-CAC9-4859-99F5-5C0D45069089} {41A5AF96-E415-4B0C-9D03-907858E23E78} {6A6A81BA-912A-485D-B57F-CCD2D37B8D94} {E4E3CF5B-97D2-4658-AACB-366E3EE2CEEE} {FD9D9559-0FD3-4917-A9A7-07E714EE9EF9} {07CFAFFB-5A2E-4B99-B62A-E4CA53B6D5AA} DXVA2_ModeVP9_VLD_Profile0 DXVA2_ModeVP9_VLD_10bit_Profile2 {76988A52-DF13-419A-8E64-FFCF4A336CF5} {68A21C7B-D58F-4E74-9993-E4B8172B19A0} {80A3A7BD-89D8-4497-A2B8-2126AF7E6EB8} {1D5C4D76-B55A-4430-904C-3383A7AE3B16} {50925B7B-E931-4978-A12A-586630F095F9} {B69C20E0-2508-8790-0305-875499E0A2D0} {49761BEC-4B63-4349-A5FF-87FFDF088466}
Deinterlace Caps: {BF752EF6-8CC4-457A-BE1B-08BD1CAEEE9F}: Format(In/Out)=(YUY2,YUY2) Frames(Prev/Fwd/Back)=(0,0,1) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_EdgeFiltering
{335AA36E-7884-43A4-9C91-7F87FAF3E37E}: Format(In/Out)=(YUY2,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_BOBVerticalStretch
{5A54A0C9-C7EC-4BD9-8EDE-F3C75DC4393B}: Format(In/Out)=(YUY2,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend

{BF752EF6-8CC4-457A-BE1B-08BD1CAEEE9F}: Format(In/Out)=(UYVY,YUY2) Frames(Prev/Fwd/Back)=(0,0,1) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_EdgeFiltering
{335AA36E-7884-43A4-9C91-7F87FAF3E37E}: Format(In/Out)=(UYVY,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_BOBVerticalStretch
{5A54A0C9-C7EC-4BD9-8EDE-F3C75DC4393B}: Format(In/Out)=(UYVY,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend
{BF752EF6-8CC4-457A-BE1B-08BD1CAEEE9F}: Format(In/Out)=(YV12,YUY2) Frames(Prev/Fwd/Back)=(0,0,1) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_EdgeFiltering
{335AA36E-7884-43A4-9C91-7F87FAF3E37E}: Format(In/Out)=(YV12,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_BOBVerticalStretch
{5A54A0C9-C7EC-4BD9-8EDE-F3C75DC4393B}: Format(In/Out)=(YV12,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend
{BF752EF6-8CC4-457A-BE1B-08BD1CAEEE9F}: Format(In/Out)=(NV12,YUY2) Frames(Prev/Fwd/Back)=(0,0,1) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_EdgeFiltering
{335AA36E-7884-43A4-9C91-7F87FAF3E37E}: Format(In/Out)=(NV12,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_BOBVerticalStretch
{5A54A0C9-C7EC-4BD9-8EDE-F3C75DC4393B}: Format(In/Out)=(NV12,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend
{BF752EF6-8CC4-457A-BE1B-08BD1CAEEE9F}: Format(In/Out)=(IMC1,YUY2) Frames(Prev/Fwd/Back)=(0,0,1) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_EdgeFiltering
{335AA36E-7884-43A4-9C91-7F87FAF3E37E}: Format(In/Out)=(IMC1,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_BOBVerticalStretch
{5A54A0C9-C7EC-4BD9-8EDE-F3C75DC4393B}: Format(In/Out)=(IMC1,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend
{BF752EF6-8CC4-457A-BE1B-08BD1CAEEE9F}: Format(In/Out)=(IMC2,YUY2) Frames(Prev/Fwd/Back)=(0,0,1) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_EdgeFiltering
{335AA36E-7884-43A4-9C91-7F87FAF3E37E}: Format(In/Out)=(IMC2,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_BOBVerticalStretch
{5A54A0C9-C7EC-4BD9-8EDE-F3C75DC4393B}: Format(In/Out)=(IMC2,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend
{BF752EF6-8CC4-457A-BE1B-08BD1CAEEE9F}: Format(In/Out)=(IMC3,YUY2) Frames(Prev/Fwd/Back)=(0,0,1) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_EdgeFiltering
{335AA36E-7884-43A4-9C91-7F87FAF3E37E}: Format(In/Out)=(IMC3,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_BOBVerticalStretch

{5A54A0C9-C7EC-4BD9-8EDE-F3C75DC4393B}: Format(In/Out)=(IMC3,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend
{BF752EF6-8CC4-457A-BE1B-08BD1CAEEE9F}: Format(In/Out)=(IMC4,YUY2) Frames(Prev/Fwd/Back)=(0,0,1) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_EdgeFiltering
{335AA36E-7884-43A4-9C91-7F87FAF3E37E}: Format(In/Out)=(IMC4,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend DeinterlaceTech_BOBVerticalStretch
{5A54A0C9-C7EC-4BD9-8EDE-F3C75DC4393B}: Format(In/Out)=(IMC4,YUY2) Frames(Prev/Fwd/Back)=(0,0,0) Caps=VideoProcess_YUV2RGB VideoProcess_StretchX VideoProcess_StretchY VideoProcess_AlphaBlend
D3D9 Overlay: Supported
DXVA-HD: Supported
DDraw Status: Enabled
D3D Status: Enabled
AGP Status: Enabled
MPO MaxPlanes: 3
MPO Caps: ROTATION,HORIZONTAL_FLIP,RGB,YUV,BILINEAR,HIGH_FILTER,STRETCH_YUV,STRETCH_RGB,IMMEDIATE,HDR (MPO3)
MPO Stretch: 21.000X - 0.334X
MPO Media Hints: rotation, colorspace Conversion
MPO Formats: NV12,YUY2,R16G16B16A16_FLOAT,R10G10B10A2_UNORM,R8G8B8A8_UNORM,B8G8R8A8_UNORM
PanelFitter Caps: ROTATION,HORIZONTAL_FLIP,RGB,YUV,BILINEAR,HIGH_FILTER,STRETCH_YUV,STRETCH_RGB,IMMEDIATE,HDR (MPO3)
PanelFitter Stretch: 21.000X - 0.334X
Extension Drivers:
Driver Name: C:\windows\System32\DriverStore\FileRepository\iigd_ext.inf_amd64_892d1d1d20845d72\iigd_ext.inf
Driver Version: 27.20.100.8853
Driver Date: 10/14/2020
Driver Provider: Intel Corporation
Catalog Attributes: Universal:N/A Declarative:True
Component Drivers:
Driver Name: Unknown
Driver Version: Unknown
Driver Date: Unknown
Driver Provider: Unknown
Catalog Attributes: N/A
Driver Name: Unknown
Driver Version: Unknown
Driver Date: Unknown
Driver Provider: Unknown
Catalog Attributes: N/A

Card name: NVIDIA GeForce MX330
Manufacturer: NVIDIA
Chip type: GeForce MX330

DAC type: Integrated RAMDAC
Device Type: Render-Only Device
Device Key: Enum\PCI\VEN_10DE&DEV_1D16&SUBSYS_868F103C&REV_A1
Device Status: 0180200A [DN_DRIVER_LOADED|DN_STARTED|DN_DISABLEABLE|
DN_NT_ENUMERATOR|DN_NT_DRIVER]
Device Problem Code: No Problem
Driver Problem Code: Unknown
Display Memory: 10019 MB
Dedicated Memory: 1983 MB
Shared Memory: 8036 MB
Current Mode: Unknown
HDR Support: Unknown
Display Topology: Unknown
Display Color Space: Unknown
Color Primaries: Unknown
Display Luminance: Unknown
Driver Name: C:\windows\System32\DriverStore\FileRepository\
nvhm.inf_amd64_58e40596c07739dd\nvldumdx.dll,C:\windows\System32\DriverStore\
FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvldumdx.dll,C:\windows\System32\
DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvldumdx.dll,C:\windows\
System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvldumdx.dll
Driver File Version: 27.21.0014.5763 (English)
Driver Version: 27.21.14.5763
DDI Version: 12
Feature Levels: 12_1,12_0,11_1,11_0,10_1,10_0,9_3,9_2,9_1
Driver Model: WDDM 2.7
Hardware Scheduling: Supported:True Enabled:False
Graphics Preemption: Pixel
Compute Preemption: Dispatch
Miracast: Not Supported by Graphics driver
Detachable GPU: No
Hybrid Graphics GPU: Discrete
Power P-states: Not Supported
Virtualization: Paravirtualization
Block List: No Blocks
Catalog Attributes: Universal:False Declarative:True
Driver Attributes: Final Retail
Driver Date/Size: 08.12.2020 02:00:00, 1039376 bytes
WHQL Logo'd: Yes
WHQL Date Stamp: Unknown
Device Identifier: Unknown
Vendor ID: 0x10DE
Device ID: 0x1D16
SubSys ID: 0x868F103C
Revision ID: 0x00A1
Driver Strong Name: oem138.inf:0f066de3651624b2:Section043:27.21.14.5763:pci\
ven_10de&dev_1d16&subsys_868f103c
Rank Of Driver: 00CF0001
Video Accel: Unknown
DXVA2 Modes: {33FCFE41-DE46-4A49-861B-AC71110649D5} {914C84A3-4078-4FA9-
984C-E2F262CB5C9C}
Deinterlace Caps: n/a

D3D9 Overlay: Unknown
DXVA-HD: Unknown
DDraw Status: Enabled
D3D Status: Enabled
AGP Status: Enabled
MPO MaxPlanes: 0
MPO Caps: Not Supported
MPO Stretch: Not Supported
MPO Media Hints: Not Supported
MPO Formats: Not Supported
PanelFitter Caps: Not Supported
PanelFitter Stretch: Not Supported

Sound Devices

Description: HP Speaker (Realtek(R) Audio)
Default Sound Playback: No
Default Voice Playback: No
Hardware ID: INTELAUDIO\
FUNC_01&VEN_10EC&DEV_0236&SUBSYS_103C868F&REV_1000
Manufacturer ID: N/A
Product ID: N/A
Type: N/A
Driver Name: RTKVHD64.sys
Driver Version: 6.0.9054.1 (English)
Driver Attributes: Final Retail
WHQL Logo'd: Yes
Date and Size: 27.10.2020 02:00:00, 5940832 bytes
Other Files:
Driver Provider: Realtek Semiconductor Corp.
HW Accel Level: Emulation Only
Cap Flags: 0xF1F
Min/Max Sample Rate: 100, 200000
Static/Strm HW Mix Bufs: 1, 0
Static/Strm HW 3D Bufs: 0, 0
HW Memory: 0
Voice Management: No
EAX(tm) 2.0 Listen/Src: No, No
I3DL2(tm) Listen/Src: No, No
Sensaura(tm) ZoomFX(tm): No

Description: LG PROJECTOR (Intel(R) Display-Audio)
Default Sound Playback: Yes
Default Voice Playback: Yes
Hardware ID: INTELAUDIO\
FUNC_01&VEN_8086&DEV_280F&SUBSYS_80860101&REV_1000
Manufacturer ID: N/A
Product ID: N/A
Type: N/A
Driver Name: IntcDAud.sys
Driver Version: 11.1.0.17 (English)

Driver Attributes: Final Retail
WHQL Logo'd: Yes
Date and Size: 16.06.2020 02:00:00, 367880 bytes
Other Files:
Driver Provider: Intel(R) Corporation
HW Accel Level: Emulation Only
Cap Flags: 0xF1F
Min/Max Sample Rate: 100, 200000
Static/Strm HW Mix Bufs: 1, 0
Static/Strm HW 3D Bufs: 0, 0
HW Memory: 0
Voice Management: No
EAX(tm) 2.0 Listen/Src: No, No
I3DL2(tm) Listen/Src: No, No
Sensaura(tm) ZoomFX(tm): No

Sound Capture Devices

Description: Microphone Array (Realtek(R) Audio)
Default Sound Capture: Yes
Default Voice Capture: Yes
Driver Name: RTKVHD64.sys
Driver Version: 6.0.9054.1 (English)
Driver Attributes: Final Retail
Date and Size: 27.10.2020 02:00:00, 5940832 bytes
Cap Flags: 0x1
Format Flags: 0xFFFFF

Video Capture Devices
Number of Devices: 1

FriendlyName: HP Webcam
Category: Camera
SymbolicLink: \\?\usb#vid_05c8&pid_0238&mi_00#6&188b67d&0&0000#{e5323777-f976-4f5b-9b55-b94699c46e44}\global
Location: Front
Rotation: 0
Manufacturer: Realtek
HardwareID: USB\VID_05C8&PID_0238&REV_0006&MI_00,USB\VID_05C8&PID_0238&MI_00
DriverDesc: Realtek DMFT - RGB
DriverProvider: Realtek
DriverVersion: 10.0.19041.20142
DriverDateEnglish: 4/28/2020 00:00:00
DriverDateLocalized: 28.04.2020 00:00:00
Service: usbvideo
Class: Camera
DevNodeStatus: 180200A[DN_DRIVER_LOADED|DN_STARTED|DN_DISABLEABLE|DN_NT_ENUMERATOR|DN_NT_DRIVER]
ContainerId: {00000000-0000-0000-FFFF-FFFFFFFFFFFF}

ProblemCode: No Problem
BusReportedDeviceDesc: HP Webcam
Parent: USB\VID_05C8&PID_0238\0x0001
DriverProblemDesc: n/a
UpperFilters: n/a
LowerFilters: WdmCompanionFilter
Stack: \FileSystem\aswSnx,\FileSystem\aswSnx,\Driver\ksthunk,\Driver\usbvideo,\
Driver\ACPI,\Driver\usbccgp
ContainerCategory: n/a
SensorGroupID: {78DCB7D0-33EA-458B-B98A-56E9A3A40B50}
MFT0: n/a
DMFT: n/a
CustomCaptureSource: n/a
DependentStillCapture: n/a
EnablePlatformDMFT: n/a
DMFTChain: n/a
EnableDshowRedirection: True
FrameServerEnabled: n/a
AnalogProviders: n/a
ProfileIDs: n/a

DirectInput Devices

Device Name: Mouse
Attached: 1
Controller ID: n/a
Vendor/Product ID: n/a
FF Driver: n/a

Device Name: Tastiera
Attached: 1
Controller ID: n/a
Vendor/Product ID: n/a
FF Driver: n/a

Device Name: HP Wireless Button Driver
Attached: 1
Controller ID: 0x0
Vendor/Product ID: 0x0001, 0x0001
FF Driver: n/a

Device Name: HIDI2C Device
Attached: 1
Controller ID: 0x0
Vendor/Product ID: 0x04F3, 0x30A0
FF Driver: n/a

Device Name: HIDI2C Device
Attached: 1
Controller ID: 0x0
Vendor/Product ID: 0x04F3, 0x30A0

FF Driver: n/a

Poll w/ Interrupt: No

USB Devices

+ Hub radice USB (USB 3.0)
| Vendor/Product ID: 0x8086, 0x34ED
| Matching Device ID: USB\ROOT_HUB30
| Service: USBHUB3
| Driver: USBHUB3.SYS, 11/19/2020 01:40:08, 647992 bytes
|
+-+ Dispositivo di input USB
| | Vendor/Product ID: 0x1EA7, 0x10C0
| | Location: Port_#0001.Hub_#0001
| | Matching Device ID: USB\Class_03&SubClass_01
| | Service: HidUsb
| | Driver: hidusb.sys, 4/14/2021 18:41:15, 44032 bytes
| | Driver: hidclass.sys, 4/14/2021 18:41:15, 225792 bytes
| | Driver: hidparse.sys, 4/14/2021 18:41:15, 46080 bytes
| |
| +-+ Mouse compatibile HID
| | | Vendor/Product ID: 0x1EA7, 0x10C0
| | | Matching Device ID: HID_DEVICE_SYSTEM_MOUSE
| | | Service: mouhid
| | | Driver: mouhid.sys, 12/7/2019 11:07:56, 35328 bytes
| | | Driver: mouclass.sys, 12/7/2019 11:07:56, 67600 bytes

Gameport Devices

PS/2 Devices

+ Tastiera standard PS/2
| Matching Device ID: *PNP0303
| Service: i8042prt
| Driver: i8042prt.sys, 12/7/2019 11:07:56, 118272 bytes
| Driver: kbdclass.sys, 12/7/2019 11:07:56, 71480 bytes
|
+ ELAN Input Device
| Vendor/Product ID: 0x04F3, 0x0000
| Matching Device ID: HID\VEN_ELAN&DEV_0723&Col01
| Upper Filters: ETD
| Service: mouhid
| Driver: ETD.sys, 9/22/2020 22:08:10, 764880 bytes
| Driver: ETDService.exe, 9/22/2020 22:08:20, 196048 bytes
| Driver: ETDCtrl.exe, 9/22/2020 22:08:14, 1241040 bytes
| Driver: ETDCtrlHelper.exe, 9/22/2020 22:08:16, 398800 bytes
| Driver: ETDCmds.dll, 9/22/2020 22:08:12, 643536 bytes

| Driver: ETDApix.dll, 9/22/2020 22:08:12, 492496 bytes
| Driver: ETDFavorite.dll, 9/22/2020 22:08:16, 470992 bytes
| Driver: mouhid.sys, 12/7/2019 11:07:56, 35328 bytes
| Driver: mouclass.sys, 12/7/2019 11:07:56, 67600 bytes

Disk & DVD/CD-ROM Drives

Drive: C:
Free Space: 269.1 GB
Total Space: 487.6 GB
File System: NTFS
Model: SK hynix BC511 HFM512GDJTNI-82A0A

System Devices

Name: Adattatore PCI standard per CPU host
Device ID: PCI\VEN_8086&DEV_8A12&SUBSYS_868F103C&REV_03\3&11583659&2&00
Driver: n/a

Name: Realtek RTL8821CE 802.11ac PCIe Adapter
Device ID: PCI\
VEN_10EC&DEV_C821&SUBSYS_831A103C&REV_00\4&22DC22F8&0&00E8
Driver: C:\windows\system32\DRIVERS\rtwlane.sys, 2024.00.0010.0220 (English), 10/15/2020 22:12:00, 11762784 bytes
Driver: C:\windows\system32\DRIVERS\rtldata.txt, 5/18/2020 09:31:06, 233450 bytes

Name: Intel(R) PCI Express Root Port #9 - 34B0
Device ID: PCI\VEN_8086&DEV_34B0&SUBSYS_868F103C&REV_30\3&11583659&2&E8
Driver: C:\windows\system32\DRIVERS\pci.sys, 10.00.19041.0662 (Italian), 1/17/2021 17:43:01, 469320 bytes

Name: Intel(R) PCI Express Root Port #5 - 34BC
Device ID: PCI\VEN_8086&DEV_34BC&SUBSYS_868F103C&REV_30\3&11583659&2&E4
Driver: C:\windows\system32\DRIVERS\pci.sys, 10.00.19041.0662 (Italian), 1/17/2021 17:43:01, 469320 bytes

Name: Intel(R) Iris(R) Plus Graphics
Device ID: PCI\VEN_8086&DEV_8A52&SUBSYS_868F103C&REV_07\3&11583659&2&10
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\igdkmdn64.sys, 27.20.0100.8853 (English), 11/19/2020 19:48:34, 26715912 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\iglhxsn64.vp, 11/19/2020 19:11:48, 6023 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\igd10iumd64.dll, 27.20.0100.8853 (English), 11/19/2020 19:48:02, 23170192 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\igd11dxva64.dll, 27.20.0100.8853 (English), 11/19/2020 19:48:18, 77702328 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igd12dxva64.dll, 27.20.0100.8853 (English), 11/19/2020 19:48:38, 77483096 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igd12umd64.dll, 27.20.0100.8853 (English), 11/19/2020 19:48:50, 22260376 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdgmm64.dll, 27.20.0100.8853 (English), 11/19/2020 19:49:44, 2519992 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igfxcmrt64.dll, 27.20.0100.8853 (English), 11/19/2020 19:50:52, 222448 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igfx11cmrt64.dll, 27.20.0100.8853 (English), 11/19/2020 19:50:42, 225624 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdumdim64.dll, 27.20.0100.8853 (English), 11/19/2020 19:50:30, 1471144 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdail64.dll, 11/19/2020 19:48:20, 201544 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igd9dxva64.dll, 27.20.0100.8853 (English), 11/19/2020 19:49:06, 77459520 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\iga64.dll, 11/19/2020 19:47:38, 2808320 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igc64.dll, 27.20.0100.8853 (English), 11/19/2020 19:47:52, 47336216 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\SPIRVDLL.dll, 11/19/2020 19:51:52, 3288904 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\UniversalAdapter64.dll, 11/19/2020 19:53:16, 518264 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\opencl-clang64.dll, 2.00.0008.0000 (English), 11/19/2020 19:53:02, 78530112 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdfcl64.dll, 27.20.0100.8853 (English), 11/19/2020 19:49:32, 1021720 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdmd64.dll, 27.20.0100.8853 (English), 11/19/2020 19:50:10, 12267472 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdml64.dll, 27.20.0100.8853 (English), 11/19/2020 19:50:20, 4341976 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdde64.dll, 27.20.0100.8853 (English), 11/19/2020 19:49:18, 431112 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdinfo64.dll, 11/19/2020 19:49:56, 163704 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdext64.dll, 27.20.0100.8853 (English), 11/19/2020 19:49:26, 460136 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igd10iumd32.dll, 27.20.0100.8853 (English), 11/19/2020 19:47:58, 19886656 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igd11dxva32.dll, 27.20.0100.8853 (English), 11/19/2020 19:48:10, 76367904 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igd12dxva32.dll, 27.20.0100.8853 (English), 11/19/2020 19:48:28, 76168672 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igd12umd32.dll, 27.20.0100.8853 (English), 11/19/2020 19:48:44, 22055920 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdgmm32.dll, 27.20.0100.8853 (English), 11/19/2020 19:49:38, 1889688 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdumdim32.dll, 27.20.0100.8853 (English), 11/19/2020 19:50:24, 1307080 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdail32.dll, 11/19/2020 19:48:14, 169800 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igd9dxva32.dll, 27.20.0100.8853 (English), 11/19/2020 19:48:58, 76137712 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igfxcmrt32.dll, 27.20.0100.8853 (English), 11/19/2020 19:50:46, 181432 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igfx11cmrt32.dll, 27.20.0100.8853 (English), 11/19/2020 19:50:36, 183592 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\iga32.dll, 11/19/2020 19:47:34, 2257480 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igc32.dll, 27.20.0100.8853 (English), 11/19/2020 19:47:46, 41391648 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\SPIRVDLL32.dll, 11/19/2020 19:51:58, 2524488 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\UniversalAdapter32.dll, 11/19/2020 19:53:12, 420952 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\opencl-clang32.dll, 2.00.0008.0000 (English), 11/19/2020 19:52:54, 58915272 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdfcl32.dll, 27.20.0100.8853 (English), 11/19/2020 19:48:24, 953160 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdmd32.dll, 27.20.0100.8853 (English), 11/19/2020 19:50:04, 9814896 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\igdml32.dll, 27.20.0100.8853 (English), 11/19/2020
19:50:14, 3280920 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\igdde32.dll, 27.20.0100.8853 (English), 11/19/2020
19:49:12, 354824 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\igdinfo32.dll, 11/19/2020 19:49:50, 141952 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\igdext32.dll, 27.20.0100.8853 (English), 11/19/2020
19:49:22, 363336 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\iglhxo64.vp, 11/19/2020 19:11:48, 42513 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\iglhxc64.vp, 11/19/2020 19:11:48, 44194 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\iglhxg64.vp, 11/19/2020 19:11:48, 43760 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\iglhxo64_dev.vp, 11/19/2020 19:11:48, 43143 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\iglhxc64_dev.vp, 11/19/2020 19:11:48, 43214 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\iglhxg64_dev.vp, 11/19/2020 19:11:48, 43732 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\iglhxa64.vp, 11/19/2020 19:11:48, 1125 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\iglhxa64.cpa, 11/19/2020 19:11:48, 1376256 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\IntelCpHDCPSvc.exe, 25.20.0100.8853 (English),
11/19/2020 19:50:22, 529672 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\cp_resources.bin, 11/19/2020 19:11:28, 2415596 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\ig11icd64.dll, 27.20.0100.8853 (English), 11/19/2020
19:47:32, 16816968 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\ig11icd32.dll, 27.20.0100.8853 (English), 11/19/2020
19:47:28, 13482824 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\OSSCOPYRIGHT, 11/19/2020 19:11:50, 1372 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\igvk64.dll, 27.20.0100.8853 (English), 11/19/2020
19:51:08, 19231448 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\igvk64.json, 11/19/2020 19:11:48, 135 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\VulkanRT-EULA.txt, 11/19/2020 19:11:50, 4008 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\igvk32.dll, 27.20.0100.8853 (English), 11/19/2020
19:51:02, 17415832 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\igvk32.json, 11/19/2020 19:11:48, 135 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\vulkan-1-64.dll, 1.02.0148.0001 (English), 11/19/2020 19:52:08, 1096312 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\vulkaninfo-64.exe, 1.02.0148.0001 (English), 11/19/2020 19:52:18, 1790216 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\vulkan-1-32.dll, 1.02.0148.0001 (English), 11/19/2020 19:52:02, 949368 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\vulkaninfo-32.exe, 1.02.0148.0001 (English), 11/19/2020 19:52:14, 1386248 bytes
Driver: C:\windows\SysWow64\vulkan-1.dll, 1.02.0148.0001 (English), 11/19/2020 19:52:02, 949368 bytes
Driver: C:\windows\SysWow64\vulkaninfo.exe, 1.02.0148.0001 (English), 11/19/2020 19:52:14, 1386248 bytes
Driver: C:\windows\SysWow64\vulkan-1-999-0-0-0.dll, 1.02.0148.0001 (English), 11/19/2020 19:52:02, 949368 bytes
Driver: C:\windows\SysWow64\vulkaninfo-1-999-0-0-0.exe, 1.02.0148.0001 (English), 11/19/2020 19:52:14, 1386248 bytes
Driver: C:\windows\system32\vulkan-1.dll, 1.02.0148.0001 (English), 11/19/2020 19:52:08, 1096312 bytes
Driver: C:\windows\system32\vulkaninfo.exe, 1.02.0148.0001 (English), 11/19/2020 19:52:18, 1790216 bytes
Driver: C:\windows\system32\vulkan-1-999-0-0-0.dll, 1.02.0148.0001 (English), 11/19/2020 19:52:08, 1096312 bytes
Driver: C:\windows\system32\vulkaninfo-1-999-0-0-0.exe, 1.02.0148.0001 (English), 11/19/2020 19:52:18, 1790216 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\Intel_OpenCL_ICD32.dll, 2.02.0008.0000 (English), 11/19/2020 19:50:42, 370504 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdrcl32.dll, 23.20.0100.8853 (English), 11/19/2020 19:48:46, 4339016 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\Intel_OpenCL_ICD64.dll, 2.02.0008.0000 (English), 11/19/2020 19:50:48, 507720 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\ze_loader.dll, 1.00.0012.0000 (English), 11/19/2020 19:52:28, 427848 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\ze_validation_layer.dll, 1.00.0012.0000 (English), 11/19/2020 19:52:32, 148808 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\igdrcl64.dll, 23.20.0100.8853 (English), 11/19/2020 19:48:52, 4945224 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\ze_intel_gpu64.dll, 11/19/2020 19:52:24, 4357448 bytes
Driver: C:\windows\SysWow64\OpenCL.dll, 2.02.0008.0000 (English), 11/19/2020 19:50:42, 370504 bytes
Driver: C:\windows\system32\OpenCL.dll, 2.02.0008.0000 (English), 11/19/2020 19:50:48, 507720 bytes

Driver: C:\windows\system32\ze_loader.dll, 1.00.0012.0000 (English), 11/19/2020 19:52:28, 427848 bytes
Driver: C:\windows\system32\ze_validation_layer.dll, 1.00.0012.0000 (English), 11/19/2020 19:52:32, 148808 bytes
Driver: C:\windows\SysWow64\libmfxhw32.dll, 11/19/2020 19:51:46, 253928 bytes
Driver: C:\windows\SysWow64\mfxplugin32_hw.dll, 1.20.0009.0015 (English), 11/19/2020 19:50:58, 13520200 bytes
Driver: C:\windows\system32\libmfxhw64.dll, 11/19/2020 19:51:52, 306016 bytes
Driver: C:\windows\system32\mfxplugin64_hw.dll, 1.20.0009.0015 (English), 11/19/2020 19:51:02, 26677064 bytes
Driver: C:\windows\system32\intel_gfx_api-x64.dll, 10.20.0009.0015 (English), 11/19/2020 19:51:12, 171488 bytes
Driver: C:\windows\SysWow64\intel_gfx_api-x86.dll, 10.20.0009.0015 (English), 11/19/2020 19:51:16, 146776 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\libmfxhw64.dll, 10.20.0009.0015 (English), 11/19/2020 19:51:28, 25487408 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfxplugin64_hw.dll, 1.20.0009.0015 (English), 11/19/2020 19:51:02, 26677064 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfxplugin64_av1e_gacc.dll, 11/19/2020 19:51:40, 8060616 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\intel_gfx_api-x64.dll, 10.20.0009.0015 (English), 11/19/2020 19:51:12, 171488 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\libmfxhw32.dll, 10.20.0009.0015 (English), 11/19/2020 19:51:22, 23997760 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfxplugin32_hw.dll, 1.20.0009.0015 (English), 11/19/2020 19:50:58, 13520200 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfxplugin32_av1e_gacc.dll, 11/19/2020 19:51:34, 6963848 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\intel_gfx_api-x86.dll, 10.20.0009.0015 (English), 11/19/2020 19:51:16, 146776 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfx_mft_h264ve_32.dll, 10.20.0009.0015 (English), 11/19/2020 19:52:20, 2625496 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfx_mft_mjpgvd_32.dll, 10.20.0009.0015 (English), 11/19/2020 19:51:08, 2463048 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfx_mft_h265ve_32.dll, 10.20.0009.0015 (English), 11/19/2020 19:52:30, 2638616 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfx_mft_vp9ve_32.dll, 10.20.0009.0015 (English), 11/19/2020 19:52:40, 2632880 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfx_mft_encrypt_32.dll, 10.20.0009.0015 (English), 11/19/2020 19:52:08, 2465744 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfx_mft_av1hve_32.dll, 10.20.0009.0015 (English), 11/19/2020 19:51:56, 2636056 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\c_32.cpa, 11/19/2020 19:11:28, 1361159 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\cpa_32.vp, 11/19/2020 19:11:28, 1125 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\dev_32.vp, 11/19/2020 19:11:28, 57143 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\he_32.vp, 11/19/2020 19:11:28, 71553 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mj_32.vp, 11/19/2020 19:11:48, 66901 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\h265e_32.vp, 11/19/2020 19:11:28, 73141 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\vp9e_32.vp, 11/19/2020 19:11:50, 72712 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfx_mft_av1hve_32.vp, 11/19/2020 19:11:48, 72825 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfx_mft_h264ve_64.dll, 10.20.0009.0015 (English), 11/19/2020 19:52:24, 3240312 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfx_mft_mjpgvd_64.dll, 10.20.0009.0015 (English), 11/19/2020 19:51:12, 3044168 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfx_mft_h265ve_64.dll, 10.20.0009.0015 (English), 11/19/2020 19:52:36, 3261952 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfx_mft_vp9ve_64.dll, 10.20.0009.0015 (English), 11/19/2020 19:52:48, 3254048 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfx_mft_encrypt_64.dll, 10.20.0009.0015 (English), 11/19/2020 19:52:14, 3035448 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mfx_mft_av1hve_64.dll, 10.20.0009.0015 (English), 11/19/2020 19:52:02, 3256720 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\c_64.cpa, 11/19/2020 19:11:28, 1376256 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\cpa_64.vp, 11/19/2020 19:11:28, 1125 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\dev_64.vp, 11/19/2020 19:11:28, 56359 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\he_64.vp, 11/19/2020 19:11:28, 13661 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iigd_dch.inf_amd64_6ce565ec54103c62\mj_64.vp, 11/19/2020 19:11:48, 13393 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\h265e_64.vp, 11/19/2020 19:11:28, 14249 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\vp9e_64.vp, 11/19/2020 19:11:50, 14096 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\
iigd_dch.inf_amd64_6ce565ec54103c62\mfx_mft_av1hve_64.vp, 11/19/2020 19:11:48, 14085
bytes

Name: Controller RAM standard PCI
Device ID: PCI\VEN_8086&DEV_34EF&SUBSYS_72708086&REV_30\3&11583659&2&A2
Driver: n/a

Name: Controller host Intel(R) USB 3.10 eXtensible - 1.10 (Microsoft)
Device ID: PCI\VEN_8086&DEV_34ED&SUBSYS_868F103C&REV_30\3&11583659&2&A0
Driver: C:\windows\system32\DRIVERS\USBXHCI.SYS, 10.00.19041.0662 (Italian), 1/17/2021
17:43:02, 602440 bytes
Driver: C:\windows\system32\DRIVERS\UMDF\UsbXhciCompanion.dll, 10.00.19041.0662
(English), 1/17/2021 17:43:02, 137936 bytes

Name: Intel(R) PCI Express Root Port #13 - 34B4
Device ID: PCI\VEN_8086&DEV_34B4&SUBSYS_868F103C&REV_30\3&11583659&2&EC
Driver: C:\windows\system32\DRIVERS\pci.sys, 10.00.19041.0662 (Italian), 1/17/2021
17:43:01, 469320 bytes

Name: Intel(R) SMBus - 34A3
Device ID: PCI\VEN_8086&DEV_34A3&SUBSYS_868F103C&REV_30\3&11583659&2&FC
Driver: n/a

Name: Controller audio della tecnologia Intel(R) Smart Sound
Device ID: PCI\VEN_8086&DEV_34C8&SUBSYS_868F103C&REV_30\3&11583659&2&FB
Driver: C:\windows\System32\DriverStore\FileRepository\
intcaudiobus.inf_amd64_9d9e7ac5673212b5\IntcAudioBus.sys, 10.24.0000.3694 (English),
4/30/2020 16:28:48, 297848 bytes
Driver: C:\windows\system32\DRIVERS\drmk.sys, 10.00.19041.0746 (English), 1/17/2021
17:43:01, 97792 bytes
Driver: C:\windows\system32\DRIVERS\portcls.sys, 10.00.19041.0746 (English), 1/17/2021
17:43:01, 388608 bytes

Name: NVIDIA GeForce MX330
Device ID: PCI\
VEN_10DE&DEV_1D16&SUBSYS_868F103C&REV_A1\4&185C86DB&0&00E4
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\
0000.ui.forms, 1/22/2021 03:16:42, 61560 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\
0000.ui.strings, 1/22/2021 03:16:42, 1404 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\
0401.ui.forms, 1/22/2021 03:16:42, 4333 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\
0401.ui.strings, 1/22/2021 03:16:42, 11724 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\
0404.ui.forms, 1/22/2021 03:16:42, 4659 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0404.ui.strings, 1/22/2021 03:16:42, 9704 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0405.ui.forms, 1/22/2021 03:16:42, 4748 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0405.ui.strings, 1/22/2021 03:16:42, 10303 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0406.ui.forms, 1/22/2021 03:16:42, 4581 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0406.ui.strings, 1/22/2021 03:16:42, 10008 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0407.ui.forms, 1/22/2021 03:16:42, 6411 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0407.ui.strings, 1/22/2021 03:16:42, 10956 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0408.ui.forms, 1/22/2021 03:16:42, 7052 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0408.ui.strings, 1/22/2021 03:16:42, 14538 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0409.ui.forms, 1/22/2021 03:16:42, 4423 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0409.ui.strings, 1/22/2021 03:16:42, 9671 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\040a.ui.forms, 1/22/2021 03:16:42, 5186 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\040a.ui.strings, 1/22/2021 03:16:42, 10352 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\040b.ui.forms, 1/22/2021 03:16:42, 6012 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\040b.ui.strings, 1/22/2021 03:16:42, 10147 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\040c.ui.forms, 1/22/2021 03:16:42, 6957 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\040c.ui.strings, 1/22/2021 03:16:42, 10826 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\040d.ui.forms, 1/22/2021 03:16:42, 4522 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\040d.ui.strings, 1/22/2021 03:16:42, 11808 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\040e.ui.forms, 1/22/2021 03:16:42, 4515 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\040e.ui.strings, 1/22/2021 03:16:42, 10454 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0410.ui.forms, 1/22/2021 03:16:42, 4704 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0410.ui.strings, 1/22/2021 03:16:42, 10535 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0411.ui.forms, 1/22/2021 03:16:42, 4700 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0411.ui.strings, 1/22/2021 03:16:42, 11814 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0412.ui.forms, 1/22/2021 03:16:42, 4567 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0412.ui.strings, 1/22/2021 03:16:42, 10625 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0413.ui.forms, 1/22/2021 03:16:42, 5913 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0413.ui.strings, 1/22/2021 03:16:42, 10358 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0414.ui.forms, 1/22/2021 03:16:42, 4770 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0414.ui.strings, 1/22/2021 03:16:42, 9998 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0415.ui.forms, 1/22/2021 03:16:42, 7010 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0415.ui.strings, 1/22/2021 03:16:42, 10351 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0416.ui.forms, 1/22/2021 03:16:42, 5603 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0416.ui.strings, 1/22/2021 03:16:42, 10202 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0419.ui.forms, 1/22/2021 03:16:42, 6039 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0419.ui.strings, 1/22/2021 03:16:42, 13126 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\041b.ui.forms, 1/22/2021 03:16:42, 4730 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\041b.ui.strings, 1/22/2021 03:16:42, 10466 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\041d.ui.forms, 1/22/2021 03:16:42, 4720 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\041d.ui.strings, 1/22/2021 03:16:42, 10030 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\041e.ui.forms, 1/22/2021 03:16:42, 5929 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\041e.ui.strings, 1/22/2021 03:16:42, 16698 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\041f.ui.forms, 1/22/2021 03:16:42, 5213 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\041f.ui.strings, 1/22/2021 03:16:42, 10165 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0424.ui.forms, 1/22/2021 03:16:42, 5495 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0424.ui.strings, 1/22/2021 03:16:42, 10187 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0804.ui.strings, 1/22/2021 03:16:42, 9154 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0809.ui.strings, 1/22/2021 03:16:42, 9639 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\080a.ui.strings, 1/22/2021 03:16:42, 10351 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0816.ui.forms, 1/22/2021 03:16:42, 5650 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\0816.ui.strings, 1/22/2021 03:16:42, 10526 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\DisplayDriver.nvi, 1/22/2021 03:16:42, 78672 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\DisplayDriverExt.dll, 2.1002.0346.0000 (English), 1/22/2021 03:36:48, 1691544 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\EULA.txt, 1/22/2021 03:16:42, 21691 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NVGPUP.Container.exe, 1.28.2851.9944 (English), 1/22/2021 03:38:30, 893848 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NVI2.dll, 2.1002.0346.0000 (English), 1/22/2021 03:38:36, 6215576 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NVI2UI.dll, 2.1002.0346.0000 (English), 1/22/2021 03:38:38, 1857776 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NVPrxy32.dll, 2.1002.0346.0000 (English), 1/22/2021 03:40:24, 1081752 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NVPrxy64.dll, 2.1002.0346.0000 (English), 1/22/2021 03:40:26, 1382808 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NVWMIExt.dll, 2.1002.0346.0000 (English), 1/22/2021 03:41:20, 1297304 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NVWmi.nvi, 1/22/2021 03:16:50, 11338 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvInstallerUtil.dll, 14.03.0041.0000 (English), 1/22/2021 03:38:46, 3567000 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Samples.7z, 1/22/2021 03:16:50, 35774 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\box_checked_disabled.png, 1/22/2021 03:16:42, 937 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\box_checked_enabled.png, 1/22/2021 03:16:42, 821 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\box_partialcheckboxed_enabled.png, 1/22/2021 03:16:42, 3208 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\box_unchecked_disabled.png, 1/22/2021 03:16:42, 180 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\box_unchecked_enabled.png, 1/22/2021 03:16:42, 701 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_disable_135.png, 1/22/2021 03:16:42, 720 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_disable_180.png, 1/22/2021 03:16:42, 738 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_disable_90.png, 1/22/2021 03:16:42, 705 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_primary_135.png, 1/22/2021 03:16:42, 870 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_primary_180.png, 1/22/2021 03:16:42, 894 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_primary_90.png, 1/22/2021 03:16:42, 852 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_primary_focus_135.png, 1/22/2021 03:16:42, 882 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_primary_focus_180.png, 1/22/2021 03:16:42, 908 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_primary_focus_90.png, 1/22/2021 03:16:42, 863 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_primary_pressed_135.png, 1/22/2021 03:16:42, 842 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_primary_pressed_180.png, 1/22/2021 03:16:42, 867 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_primary_pressed_90.png, 1/22/2021 03:16:42, 822 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_secondary_135.png, 1/22/2021 03:16:42, 815 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_secondary_180.png, 1/22/2021 03:16:42, 833 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_secondary_90.png, 1/22/2021 03:16:42, 796 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_secondary_focus_135.png, 1/22/2021 03:16:42, 801 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_secondary_focus_180.png, 1/22/2021 03:16:42, 824 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_secondary_focus_90.png, 1/22/2021 03:16:42, 789 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_secondary_pressed_135.png, 1/22/2021 03:16:42, 819 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_secondary_pressed_180.png, 1/22/2021 03:16:42, 841 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\btn_secondary_pressed_90.png, 1/22/2021 03:16:42, 803 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\check.png, 1/22/2021 03:16:42, 731 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\checkmark.png, 1/22/2021 03:16:42, 641 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\circled_checkmark.png, 1/22/2021 03:16:42, 2970 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\dbInstaller.exe, 27.21.0014.5763 (English), 1/22/2021 03:36:48, 730008 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\error.png, 1/22/2021 03:16:42, 2531 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\flxcomm64.dll, 2018.02.0001.0000 (English), 1/22/2021 03:36:50, 3023000 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\flxconnect64.dll, 2018.02.0001.0000 (English), 1/22/2021 03:36:54, 6594200 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\flxcore64.dll, 2018.02.0001.0000 (English), 1/22/2021 03:36:58, 8967832 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\info.png, 1/22/2021 03:16:42, 2191 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\install_bg.png, 1/22/2021 03:16:42, 62330 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\install_bg_rtl.png, 1/22/2021 03:16:42, 63022 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\license.txt, 1/22/2021 03:16:42, 27216 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\mcu.exe, 1.01.5204.20580 (German), 1/22/2021 03:37:02, 850840 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvPerfProvider.man, 1/22/2021 03:16:48, 14175 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvWmi.chm, 1/22/2021 03:16:50, 369111 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvWmi.mof, 1/22/2021 03:16:50, 147847 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvWmi64.exe, 2.35.0000.0000 (English), 1/22/2021 03:41:18, 4808600 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvapi.dll, 27.21.0014.5763 (English), 1/22/2021 03:36:12, 5978008 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvapi64.dll, 27.21.0014.5763 (English), 1/22/2021 03:36:14, 7006712 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvcuda_loader32.dll, 27.21.0014.5763 (English), 1/22/2021 03:37:46, 4175256 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvcuda_loader64.dll, 27.21.0014.5763 (English), 1/22/2021 03:37:48, 2508528 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvcuvid32.dll, 7.17.0014.5763 (English), 1/22/2021 03:37:50, 6858992 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvcuvid64.dll, 7.17.0014.5763 (English), 1/22/2021 03:37:54, 7706352 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvdebugdump.exe, 6.14.0014.5763 (English), 1/22/2021 03:37:56, 445848 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvdrsdb.bin, 1/22/2021 03:16:42, 1717136 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvencodeapi.dll, 27.21.0014.5763 (English), 1/22/2021 03:38:20, 657304 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvencodeapi64.dll, 27.21.0014.5763 (English), 1/22/2021 03:38:20, 813464 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvfbc.dll, 6.14.0014.5763 (English), 1/22/2021 03:38:22, 1585560 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvfbc64.dll, 6.14.0014.5763 (English), 1/22/2021 03:38:24, 2098072 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvhm.inf, 1/22/2021 03:16:44, 949227 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvidia-smi.exe, 8.17.0014.5763 (English), 1/22/2021 03:38:40, 591768 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvifr.dll, 6.14.0014.5763 (English), 1/22/2021 03:38:40, 1161112 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvifr64.dll, 6.14.0014.5763 (English), 1/22/2021 03:38:42, 1507224 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvifropengl32.dll, 27.21.0014.5763 (English), 1/22/2021 03:38:44, 556440 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvifropengl64.dll, 27.21.0014.5763 (English), 1/22/2021 03:38:46, 670616 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvinfo.pb, 1/22/2021 03:16:44, 81090 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvmcumd.dll, 27.21.0014.5763 (English), 1/22/2021 03:38:58, 816368 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvml.dll, 8.17.0014.5763 (English), 1/22/2021 03:39:00, 1027992 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvofapi.dll, 1/22/2021 03:39:04, 543128 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvofapi64.dll, 1/22/2021 03:39:06, 674712 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvsetup.exe, 1/22/2021 03:40:48, 84888 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvvgpu64.dll, 6.14.0014.5763 (English), 1/22/2021 03:41:12, 1853336 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvvgpuconfig.dll, 27.21.0014.5763 (English), 1/22/2021 03:41:14, 292248 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\opencl32.dll, 2.02.0005.0000 (English), 1/22/2021 03:41:32, 349936 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\opencl64.dll, 2.02.0005.0000 (English), 1/22/2021 03:41:32, 456600 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\presentations_bg.png, 1/22/2021 03:16:50, 143326 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\presentations_bg_rtl.png, 1/22/2021 03:16:50, 140906 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\radio_btn_selected.png, 1/22/2021 03:16:50, 1718 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\radio_btn_unselected.png, 1/22/2021 03:16:50, 1516 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\setup.cfg, 1/22/2021 03:16:50, 12882 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\setup.exe, 2.1002.0346.0000 (English), 1/22/2021 03:41:34, 514456 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\splash.png, 1/22/2021 03:16:50, 161756 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\splash_rtl.png, 1/22/2021 03:16:50, 164925 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\theme.cfg, 1/22/2021 03:16:50, 8943 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\uninstall_bg.png, 1/22/2021 03:16:50, 64596 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\uninstall_bg_rtl.png, 1/22/2021 03:16:50, 62297 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\vgpuconfig.xml, 1/22/2021 03:16:50, 419989 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\vulkan-1-x64.dll, 1.02.0141.0000 (English), 1/22/2021 03:41:38, 1054944 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\vulkan-1-x86.dll, 1.02.0141.0000 (English), 1/22/2021 03:41:40, 917728 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\vulkaninfo-x64.exe, 1.02.0141.0000 (English), 1/22/2021 03:41:40, 1769688 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\vulkaninfo-x86.exe, 1.02.0141.0000 (English), 1/22/2021 03:41:42, 1370328 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\warning.png, 1/22/2021 03:16:50, 1601 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\MessageBus.dll, 1.22.2758.1620 (English), 1/22/2021 03:41:44, 7533296 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\NVDisplay.Container.exe, 1.28.2851.9944 (English), 1/22/2021 03:41:46, 893848 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\NvContainerRecovery.bat, 1/22/2021 03:16:50, 1951 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\messagebus_client.conf, 1/22/2021 03:16:50, 57 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\nvgwls.exe, 1/22/2021 03:41:46, 39647472 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\nvtopps.db3, 1/22/2021 03:16:50, 81920 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\plugins\LocalSystem\NvXDCore.dll, 27.21.0014.5763 (English), 1/22/2021 03:41:50, 1781488 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\plugins\LocalSystem\NvcDispCorePlugin.dll, 27.21.0014.5763 (English), 1/22/2021 03:41:48, 520432 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\plugins\LocalSystem\NvcDispWatchdog.dll, 1.28.2851.9944 (English), 1/22/2021 03:41:48, 629656 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\plugins\LocalSystem_DisplayDriverRAS.dll, 1.10.0000.0000 (English), 1/22/2021 03:41:50, 2569968 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\plugins\LocalSystem_NvMessageBusBroadcast.dll, 1.28.2851.9944 (English), 1/22/2021 03:41:52, 3154840 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\plugins\LocalSystem\messagebus.conf, 1/22/2021 03:16:50, 57 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\plugins\Session\NvFBCPlugin.dll, 6.14.0014.5763 (English), 1/22/2021 03:41:52, 1357040 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\plugins\Session_nvppo.dll, 27.21.0014.5763 (English), 1/22/2021 03:41:56, 1603480 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\plugins\Session_nvtopps.dll, 27.21.0014.5763 (English), 1/22/2021 03:41:58, 8469400 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\plugins\Session\nvprofileupdaterplugin.dll, 27.21.0014.5763 (English), 1/22/2021 03:41:54, 2163440 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\plugins\Session\nvxdsyncplugin.dll, 8.17.0014.5763 (English), 1/22/2021 03:41:54, 1800600 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\Display.NvContainer\plugins\Session\wksServicePlugin.dll, 27.21.0014.5763 (English), 1/22/2021 03:41:56, 570776 bytes
Driver: C:\windows\system32\DRIVERS\NVIDIA Corporation\Drs\dbInstaller.exe, 27.21.0014.5763 (English), 1/22/2021 03:36:48, 730008 bytes
Driver: C:\windows\system32\DRIVERS\NVIDIA Corporation\Drs\nvdrsdb.bin, 1/22/2021 03:16:42, 1717136 bytes
Driver: C:\windows\system32\nvcpl.dll, 8.17.0014.4183 (English), 1/20/2020 20:56:24, 5582256 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nv3dappshext.dll, 6.14.0014.5763 (English), 1/22/2021 03:37:04, 1000856 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nv3dappshextr.dll, 6.14.0014.5763 (Italian), 1/22/2021 03:37:06, 91888 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvcoproc.bin, 1/22/2021 03:16:42, 9371667 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvcpl.dll, 8.17.0014.5763 (English), 1/22/2021 03:37:32, 5527792 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvdevtools.dll, 27.21.0014.5763 (English), 1/22/2021 03:38:00, 4536728 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvdevtoolsr.dll, 27.21.0014.5763 (Italian), 1/22/2021 03:38:02, 234392 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvdisps.dll, 27.21.0014.5763 (English), 1/22/2021 03:38:06, 11583896 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvdispsr.dll, 27.21.0014.5763 (Italian), 1/22/2021 03:38:06, 11146480 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvgames.dll, 27.21.0014.5763 (English), 1/22/2021 03:38:24, 12308208 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvgamesr.dll, 27.21.0014.5763 (Italian), 1/22/2021 03:38:26, 12448496 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvlicensings.dll, 6.14.0014.5763 (English), 1/22/2021 03:38:56, 4539632 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvlicensingsr.dll, 6.14.0014.5763 (Italian), 1/22/2021 03:38:58, 292760 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvshext.dll, 1.02.0000.0001 (English), 1/22/2021 03:40:54, 130968 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvsmartmax.dll, 6.14.0010.10003 (English), 1/22/2021 03:40:54, 202992 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvsmartmax64.dll, 6.14.0010.10003 (English), 1/22/2021 03:40:56, 242416 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvsmartmaxapp.exe, 6.14.0010.10003 (English), 1/22/2021 03:40:58, 274328 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvsmartmaxapp64.exe, 6.14.0010.10003 (English), 1/22/2021 03:40:58, 285080 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvsvc64.dll, 27.21.0014.5763 (German), 1/22/2021 03:41:00, 2644888 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvsvcr.dll, 27.21.0014.5763 (German), 1/22/2021 03:41:02, 1768856 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvsvs.dll, 27.21.0014.5763 (English), 1/22/2021 03:41:04, 5054704 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvsvsr.dll, 27.21.0014.5763 (English), 1/22/2021 03:41:04, 1948056 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvui.dll, 8.17.0014.5763 (English), 1/22/2021 03:41:08, 6567664 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvuir.dll, 8.17.0014.5763 (Italian), 1/22/2021 03:41:10, 2490608 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvvitvs.dll, 27.21.0014.5763 (English), 1/22/2021 03:41:16, 7399832 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvvitvsr.dll, 27.21.0014.5763 (Italian), 1/22/2021 03:41:16, 4113816 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvwss.dll, 27.21.0014.5763 (English), 1/22/2021 03:41:20, 12064496 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvwssr.dll, 27.21.0014.5763 (Italian), 1/22/2021 03:41:22, 9347480 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvxdapix.dll, 8.17.0014.5763 (English), 1/22/2021 03:41:26, 9042840 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvxdbat.dll, 8.17.0014.5763 (English), 1/22/2021 03:41:28, 1606896 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvxdplcy.dll, 8.17.0014.5763 (English), 1/22/2021 03:41:30, 1857432 bytes
Driver: C:\windows\system32\DRIVERS\NVIDIA Corporation\license.txt, 1/20/2020 20:56:19, 27216 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Adjustments.yaml, 1/22/2021 03:16:50, 8964 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Adjustments.yfx, 1/22/2021 03:16:50, 1271 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\BlacknWhite.yaml, 1/22/2021 03:16:50, 5774 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\BlacknWhite.yfx, 1/22/2021 03:16:50, 1080 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Color.yaml, 1/22/2021 03:16:50, 5298 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Color.yfx, 1/22/2021 03:16:50, 1951 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Colorblind.yaml, 1/22/2021 03:16:50, 3853 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Colorblind.yfx, 1/22/2021 03:16:50, 1531 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\DOF.yaml, 1/22/2021 03:16:50, 16008 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\DOF.yfx, 1/22/2021 03:16:50, 12413 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Details.yaml, 1/22/2021 03:16:50, 5222 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Details.yfx, 1/22/2021 03:16:50, 4077 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\FreqTransfer32.exe, 1/22/2021 03:42:00, 3722480 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\FreqTransfer64.exe, 1/22/2021 03:42:02, 4067736 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\GreenScreen.yaml, 1/22/2021 03:16:50, 5882 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\GreenScreen.yfx, 1/22/2021 03:16:50, 2034 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\GreenScreenBG01.jpg, 1/22/2021 03:16:50, 281528 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\GreenScreenBG02.jpg, 1/22/2021 03:16:50, 499736 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\HighresBlender32.exe, 1/22/2021 03:42:02, 3828464 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\HighresBlender64.exe, 1/22/2021 03:42:04, 4186352 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\LDR_RGB1_18.png, 1/22/2021 03:16:50, 3671 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Letterbox.yaml, 1/22/2021 03:16:50, 3295 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Letterbox.yfx, 1/22/2021 03:16:50, 1319 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\NightMode.yaml, 1/22/2021 03:16:50, 1738 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\NightMode.yfx, 1/22/2021 03:16:50, 552 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\NvCamera32.dll, 7.00.0636.0672 (English), 1/22/2021 03:42:04, 6976920 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\NvCamera64.dll, 7.00.0636.0672 (English), 1/22/2021 03:42:06, 7867120 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\NvCameraAllowlisting32.dll, 7.00.0636.0672 (English), 1/22/2021 03:42:08, 555760 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\NvCameraAllowlisting64.dll, 7.00.0636.0672 (English), 1/22/2021 03:42:08, 697752 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\NvCameraEnable.exe, 1/22/2021 03:42:08, 371096 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\NvImageConvert32.exe, 1/22/2021 03:42:10, 3749272 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\NvImageConvert64.exe, 1/22/2021 03:42:10, 4080368 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\OldFilm.yaml, 1/22/2021 03:16:50, 7473 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\OldFilm.yfx, 1/22/2021 03:16:50, 2746 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Posterize.fx, 1/22/2021 03:16:50, 12310 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\ReShadeFXC32.exe, 2.00.0000.0000 (English), 1/22/2021 03:42:12, 725912 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\RemoveHud.yaml, 1/22/2021 03:16:50, 459 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\RemoveHud.yfx, 1/22/2021 03:16:50, 776 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Sharpen.yaml, 1/22/2021 03:16:52, 3030 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Sharpen.yfx, 1/22/2021 03:16:52, 4993 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\ShotWithGeforce518x32.rgba, 1/22/2021 03:16:52, 66304 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\SpecialFX.yaml, 1/22/2021 03:16:52, 14100 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\SpecialFX.yfx, 1/22/2021 03:16:52, 13357 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\SphericalEquirect32.exe, 1/22/2021 03:42:12, 3699440 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\SphericalEquirect64.exe, 1/22/2021 03:42:14, 3983768 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Splitscreen.yaml, 1/22/2021 03:16:52, 9609 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Splitscreen.yfx, 1/22/2021 03:16:52, 7203 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Sticker01.png, 1/22/2021 03:16:52, 49695 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Sticker02.png, 1/22/2021 03:16:52, 474002 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Sticker03.png, 1/22/2021 03:16:52, 380006 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Sticker04.png, 1/22/2021 03:16:52, 86881 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Sticker05.png, 1/22/2021 03:16:52, 59304 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Sticker06.png, 1/22/2021 03:16:52, 13547 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Sticker07.png, 1/22/2021 03:16:52, 6342 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Sticker08.png, 1/22/2021 03:16:52, 96493 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Stickers.yaml, 1/22/2021 03:16:52, 10323 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Stickers.yfx, 1/22/2021 03:16:52, 3989 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\TiltShift.yaml, 1/22/2021 03:16:52, 4656 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\TiltShift.yfx, 1/22/2021 03:16:52, 4849 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Vignette.yaml, 1/22/2021 03:16:52, 4677 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\Vignette.yfx, 1/22/2021 03:16:52, 1823 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\YAMLFXC32.exe, 1/22/2021 03:42:14, 1066736 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\d3dcompiler_47_32.dll, 6.03.9600.16384 (English), 1/22/2021 03:41:58, 3468696 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\d3dcompiler_47_64.dll, 6.03.9600.16384 (English), 1/22/2021 03:42:00, 4175768 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\filternames.cfg, 1/22/2021 03:16:50, 14012 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\fxtools.cfg, 1/22/2021 03:16:50, 65 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\scratches.jpg, 1/22/2021 03:16:52, 346354 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\tools_licenses.txt, 1/22/2021 03:16:52, 12616 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvCamera\ui.tga, 1/22/2021 03:16:52, 120236 bytes
Driver: C:\windows\system32\MCU.exe, 1.01.5204.20580 (German), 1/22/2021 03:37:02, 850840 bytes
Driver: C:\windows\system32\nvdebugdump.exe, 6.14.0014.5763 (English), 1/22/2021 03:37:56, 445848 bytes
Driver: C:\windows\system32\nvidia-smi.exe, 8.17.0014.5763 (English), 1/22/2021 03:38:40, 591768 bytes
Driver: C:\windows\system32\nvml.dll, 8.17.0014.5763 (English), 1/22/2021 03:39:00, 1027992 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvopencl32.dll, 27.21.0014.5763 (English), 1/22/2021 03:39:30, 33987312 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvopencl64.dll, 27.21.0014.5763 (English), 1/22/2021 03:39:40, 39601560 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvcompiler32.dll, 27.21.0014.5763 (English), 1/22/2021 03:37:12, 35489008 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvcompiler64.dll, 27.21.0014.5763 (English), 1/22/2021 03:37:22, 40632560 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvlddmkm.sys, 27.21.0014.5763 (English), 1/22/2021 03:38:48, 33070488 bytes
Driver: C:\windows\system32\DRIVERS\nvlddmkm.sys, 27.21.0014.5763 (English), 1/22/2021 03:38:48, 33070488 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nv-vk64.json, 1/22/2021 03:16:42, 671 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvDecMFTMjpeg.dll, 27.21.0014.5763 (English), 1/22/2021 03:37:58, 604568 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvDecMFTMjpegx.dll, 27.21.0014.5763 (English), 1/22/2021 03:37:58, 746904 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvcbl64.dll, 27.21.0014.5763 (English), 1/22/2021 03:37:08, 684440 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvcuda32.dll, 27.21.0014.5763 (English), 1/22/2021 03:37:34, 19287448 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvcuda64.dll, 27.21.0014.5763 (English), 1/22/2021 03:37:40, 22070000 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvd3dumx.dll, 27.21.0014.5763 (English), 1/22/2021 03:36:26, 27721784 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvd3dumx_cfg.dll, 27.21.0014.5763 (English), 1/22/2021 03:36:34, 27952072 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvdlistx.dll, 27.21.0014.5763 (English), 1/22/2021 03:38:10, 209136 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvldumdx.dll, 27.21.0014.5763 (English), 1/22/2021 03:36:50, 1039376 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvoglv64.dll, 27.21.0014.5763 (English), 1/22/2021 03:39:18, 46766832 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvoptix.dll, 7.02.0000.0000 (English), 1/22/2021 03:39:54, 155447192 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvptxJitCompiler32.dll, 27.21.0014.5763 (English), 1/22/2021 03:40:28, 8485272 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvptxJitCompiler64.dll, 27.21.0014.5763 (English), 1/22/2021 03:40:32, 9087384 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvrtum64.dll, 27.21.0014.5763 (English), 1/22/2021 03:40:36, 53091568 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvwgf2umx.dll, 27.21.0014.5763 (English), 1/22/2021 03:37:06, 45018032 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvwgf2umx_cfg.dll, 27.21.0014.5763 (English), 1/22/2021 03:37:20, 45408296 bytes
Driver: C:\windows\system32\NvFBC64.dll, 6.14.0014.5763 (English), 1/22/2021 03:38:24, 2098072 bytes
Driver: C:\windows\system32\NvIFR64.dll, 6.14.0014.5763 (English), 1/22/2021 03:38:42, 1507224 bytes
Driver: C:\windows\system32\NvIFROpenGL.dll, 27.21.0014.5763 (English), 1/22/2021 03:38:46, 670616 bytes
Driver: C:\windows\system32\OpenCL.dll, 2.02.0008.0000 (English), 11/19/2020 19:50:48, 507720 bytes

Driver: C:\windows\system32\nvapi64.dll, 27.21.0014.5763 (English), 1/22/2021 03:36:14, 7006712 bytes
Driver: C:\windows\system32\nvcuda.dll, 27.21.0014.5763 (English), 1/22/2021 03:37:48, 2508528 bytes
Driver: C:\windows\system32\nvcuvid.dll, 7.17.0014.5763 (English), 1/22/2021 03:37:54, 7706352 bytes
Driver: C:\windows\system32\nvinfo.pb, 1/22/2021 03:16:44, 81090 bytes
Driver: C:\windows\system32\nvofapi64.dll, 1/22/2021 03:39:06, 674712 bytes
Driver: C:\windows\system32\vulkan-1-999-0-0-0.dll, 1.02.0148.0001 (English), 11/19/2020 19:52:08, 1096312 bytes
Driver: C:\windows\system32\vulkan-1.dll, 1.02.0148.0001 (English), 11/19/2020 19:52:08, 1096312 bytes
Driver: C:\windows\system32\vulkaninfo-1-999-0-0-0.exe, 1.02.0148.0001 (English), 11/19/2020 19:52:18, 1790216 bytes
Driver: C:\windows\system32\vulkaninfo.exe, 1.02.0148.0001 (English), 11/19/2020 19:52:18, 1790216 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nv-vk32.json, 1/22/2021 03:16:42, 671 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvIccAdvancedColorIdentity.icm, 1/22/2021 03:16:44, 3288 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvd3dum.dll, 27.21.0014.5763 (English), 1/22/2021 03:36:18, 23442184 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvd3dum_cfg.dll, 27.21.0014.5763 (English), 1/22/2021 03:36:42, 23825960 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvdispco64.exe, 1.00.0015.0000 (English), 1/22/2021 03:38:04, 1536240 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvdlist.dll, 27.21.0014.5763 (English), 1/22/2021 03:38:10, 176880 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvldumd.dll, 27.21.0014.5763 (English), 1/22/2021 03:36:48, 862656 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvoglv32.dll, 27.21.0014.5763 (English), 1/22/2021 03:39:08, 36324760 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvwgf2um.dll, 27.21.0014.5763 (English), 1/22/2021 03:36:54, 39825472 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\nvwgf2um_cfg.dll, 27.21.0014.5763 (English), 1/22/2021 03:37:34, 40458952 bytes
Driver: C:\windows\SysWow64\NvFBC.dll, 6.14.0014.5763 (English), 1/22/2021 03:38:22, 1585560 bytes
Driver: C:\windows\SysWow64\NvIFR.dll, 6.14.0014.5763 (English), 1/22/2021 03:38:40, 1161112 bytes
Driver: C:\windows\SysWow64\NvIFROpenGL.dll, 27.21.0014.5763 (English), 1/22/2021 03:38:44, 556440 bytes
Driver: C:\windows\SysWow64\OpenCL.dll, 2.02.0008.0000 (English), 11/19/2020 19:50:42, 370504 bytes
Driver: C:\windows\SysWow64\nvapi.dll, 27.21.0014.5763 (English), 1/22/2021 03:36:12, 5978008 bytes
Driver: C:\windows\SysWow64\nvcuda.dll, 27.21.0014.5763 (English), 1/22/2021 03:37:46, 4175256 bytes
Driver: C:\windows\SysWow64\nvcuvid.dll, 7.17.0014.5763 (English), 1/22/2021 03:37:50, 6858992 bytes
Driver: C:\windows\SysWow64\nvofapi.dll, 1/22/2021 03:39:04, 543128 bytes

Driver: C:\windows\SysWow64\vulkan-1-999-0-0-0.dll, 1.02.0148.0001 (English), 11/19/2020 19:52:02, 949368 bytes
Driver: C:\windows\SysWow64\vulkan-1.dll, 1.02.0148.0001 (English), 11/19/2020 19:52:02, 949368 bytes
Driver: C:\windows\SysWow64\vulkaninfo-1-999-0-0-0.exe, 1.02.0148.0001 (English), 11/19/2020 19:52:14, 1386248 bytes
Driver: C:\windows\SysWow64\vulkaninfo.exe, 1.02.0148.0001 (English), 11/19/2020 19:52:14, 1386248 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\nvhm.inf_amd64_58e40596c07739dd\NvTelemetry64.dll, 14.03.0054.0000 (English), 1/22/2021 03:41:06, 4548496 bytes

Name: Intel(R) PCI Express Root Port #4 - 34BB
Device ID: PCI\VEN_8086&DEV_34BB&SUBSYS_868F103C&REV_30\3&11583659&2&E0
Driver: C:\windows\system32\DRIVERS\pci.sys, 10.00.19041.0662 (Italian), 1/17/2021 17:43:01, 469320 bytes

Name: Intel(R) Serial IO I2C Host Controller - 34E8
Device ID: PCI\VEN_8086&DEV_34E8&SUBSYS_868F103C&REV_30\3&11583659&2&A8
Driver: C:\windows\System32\DriverStore\FileRepository\ialpss2_i2c_icl.inf_amd64_c8c0638291b9b209\iaLPSS2_I2C_ICL.sys, 30.100.2010.0001 (English), 4/28/2020 00:18:14, 200456 bytes

Name: Intel(R) Dynamic Tuning Processor Participant
Device ID: PCI\VEN_8086&DEV_8A03&SUBSYS_868F103C&REV_03\3&11583659&2&20
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\esif_lf.sys, 8.07.10401.16510 (English), 8/27/2020 10:14:04, 420008 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\dptf_cpu.sys, 8.07.10401.16510 (English), 8/27/2020 10:14:02, 73384 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\esif_uf.exe, 8.07.10401.16510 (English), 8/27/2020 10:14:04, 2263208 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\esif_umdf2.dll, 8.07.10401.16510 (English), 8/27/2020 10:14:06, 988328 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\Dptf.dll, 8.07.10401.16510 (English), 8/27/2020 10:13:54, 2406568 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\DptfPolicyRfim.dll, 8.07.10401.16510 (English), 8/27/2020 10:14:00, 793768 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\DptfPolicyActive.dll, 8.07.10401.16510 (English), 8/27/2020 10:13:56, 806568 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\DptfPolicyActive2.dll, 8.07.10401.16510 (English), 8/27/2020 10:13:56, 988840 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\DptfPolicyAdaptiveUserPresence.dll, 8.07.10401.16510 (English), 8/27/2020 10:13:56, 981160 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\DptfPolicyAdaptivePerformance.dll, 8.07.10401.16510 (English), 8/27/2020 10:13:56, 1183912 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\DptfPolicyCritical.dll, 8.07.10401.16510 (English), 8/27/2020 10:13:56, 784040 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\DptfPolicyPassive.dll, 8.07.10401.16510 (English), 8/27/2020 10:13:58, 1116328 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\DptfPolicyPassive2.dll, 8.07.10401.16510 (English), 8/27/2020 10:13:58, 1041064 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\DptfPolicyPid.dll, 8.07.10401.16510 (English), 8/27/2020 10:13:58, 963240 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\DptfPolicyPowerBoss.dll, 8.07.10401.16510 (English), 8/27/2020 10:13:58, 1399976 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\DptfPolicyVirtualSensor.dll, 8.07.10401.16510 (English), 8/27/2020 10:14:02, 949416 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\DptfPolicyPowerShare.dll, 8.07.10401.16510 (English), 8/27/2020 10:14:00, 944296 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\DptfPolicyPowerShare2.dll, 8.07.10401.16510 (English), 8/27/2020 10:14:00, 960168 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\DptfPolicySystemConfiguration.dll, 8.07.10401.16510 (English), 8/27/2020 10:14:00, 750760 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\upe_wwan.dll, 8.07.10401.16510 (English), 8/27/2020 10:14:10, 132776 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\upe_wifi.dll, 8.07.10401.16510 (English), 8/27/2020 10:14:08, 66728 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\upe_nvme.dll, 8.07.10401.16510 (English), 8/27/2020 10:14:08, 114344 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\upe_battery.dll, 8.07.10401.16510 (English), 8/27/2020 10:14:06, 71336 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\upe_socwc.dll, 8.07.10401.16510 (English), 8/27/2020 10:14:08, 224936 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\upe_hwpf.dll, 8.07.10401.16510 (English), 8/27/2020 10:14:08, 73896 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\dptf_helper.exe, 8.07.10401.16510 (English), 8/27/2020 10:14:04, 539816 bytes

Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\esif_cmp.dll, 8.07.10401.16510 (English), 8/27/2020 10:14:04, 138408 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\esif_ws.dll, 8.07.10401.16510 (English), 8/27/2020 10:14:06, 230568 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\dptf_cpu.inf_amd64_e3868713e3d137ef\dsp.dv, 8/27/2020 10:03:12, 877280 bytes

Name: Intel(R) Chipset SATA/PCIe RST Premium Controller
Device ID: PCI\VEN_8086&DEV_282A&SUBSYS_868F103C&REV_30\3&11583659&2&B8
Driver: C:\windows\system32\DRIVERS\iaStorAC.sys, 17.09.0001.1009 (English), 7/9/2020 10:19:18, 1348576 bytes
Driver: C:\windows\system32\DRIVERS\iaStorAfs.sys, 17.09.0001.1009 (English), 7/9/2020 10:19:20, 74208 bytes
Driver: C:\windows\system32\iaStorAfsService.exe, 17.09.0001.1009 (English), 7/9/2020 10:19:22, 2924000 bytes
Driver: C:\windows\system32\iaStorAfsNative.exe, 17.09.0001.1009 (English), 7/9/2020 10:19:20, 220640 bytes
Driver: C:\windows\system32\OptaneEventLogMsg.dll, 17.09.0001.1009 (English), 7/9/2020 10:19:22, 24544 bytes
Driver: C:\windows\system32\Optane.dll, 17.09.0001.1009 (English), 7/9/2020 10:19:22, 115168 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iastorac.inf_amd64_42f9d9bfb72d84cf\HfcDisableService.exe, 17.09.0001.1009 (English), 7/9/2020 10:19:18, 1917920 bytes
Driver: C:\windows\System32\DriverStore\FileRepository\iastorac.inf_amd64_42f9d9bfb72d84cf\RstMwService.exe, 17.09.0001.1009 (English), 7/9/2020 10:19:24, 2245088 bytes
Driver: C:\windows\system32\RstMwEventLogMsg.dll, 17.09.0001.1009 (English), 7/9/2020 10:19:24, 27616 bytes

Name: Realtek PCIe GbE Family Controller
Device ID: PCI\VEN_10EC&DEV_8168&SUBSYS_868F103C&REV_15\4&3B1A5057&0&00E0
Driver: C:\windows\system32\DRIVERS\rt640x64.sys, 10.39.0212.2020 (German), 9/29/2020 02:26:14, 1162848 bytes

Name: Intel(R) Management Engine Interface #1
Device ID: PCI\VEN_8086&DEV_34E0&SUBSYS_868F103C&REV_30\3&11583659&2&B0
Driver: C:\windows\System32\DriverStore\FileRepository\heci.inf_amd64_3fec17f874687c29\x64\TeeDriverW10x64.sys, 2035.15.0000.1807 (English), 9/3/2020 03:48:22, 304648 bytes

Name: Controller Standard NVM Express
Device ID: PCI\VEN_1C5C&DEV_1339&SUBSYS_00001C5C&REV_00\4&2702BE5F&0&00EC
Driver: C:\windows\system32\DRIVERS\stornvme.sys, 10.00.19041.0844 (English), 3/10/2021 16:04:35, 155960 bytes

Name: I/O LPC Controller (U Premium) - 3482 for Intel(R) On-Package Platform Controller Hub
Device ID: PCI\VEN_8086&DEV_3482&SUBSYS_868F103C&REV_30\3&11583659&2&F8

Driver: C:\windows\system32\DRIVERS\msisadrv.sys, 10.00.19041.0001 (English), 12/7/2019 11:07:54, 20280 bytes

Name: Intel(R) SPI (flash) Controller - 34A4
Device ID: PCI\VEN_8086&DEV_34A4&SUBSYS_868F103C&REV_30\3&11583659&2&FD
Driver: n/a

DirectShow Filters

DirectShow Filters:
WMAudio Decoder DMO,0x00800800,1,1,WMADMOD.DLL,10.00.19041.0508
WMAPro over S/PDIF DMO,0x00600800,1,1,WMADMOD.DLL,10.00.19041.0508
WMSpeech Decoder DMO,0x00600800,1,1,WMSPDMOD.DLL,10.00.19041.0001
MP3 Decoder DMO,0x00600800,1,1,mp3dmod.dll,10.00.19041.0001
Mpeg4s Decoder DMO,0x00800001,1,1,mp4sdecd.dll,10.00.19041.0450
WMV Screen decoder DMO,0x00600800,1,1,wmvsdecd.dll,10.00.19041.0001
WMVideo Decoder DMO,0x00800001,1,1,wmvdecod.dll,10.00.19041.0928
Mpeg43 Decoder DMO,0x00800001,1,1,mp43decd.dll,10.00.19041.0001
Mpeg4 Decoder DMO,0x00800001,1,1,mpg4decd.dll,10.00.19041.0001
DV Muxer,0x00400000,0,0,qdv.dll,10.00.19041.0001
Color Space Converter,0x00400001,1,1,quartz.dll,10.00.19041.0746
WM ASF Reader,0x00400000,0,0,qasf.dll,12.00.19041.0001
AVI Splitter,0x00600000,1,1,quartz.dll,10.00.19041.0746
VGA 16 Color Ditherer,0x00400000,1,1,quartz.dll,10.00.19041.0746
SBE2MediaTypeProfile,0x00200000,0,0,sbe.dll,10.00.19041.0001
Microsoft DTV-DVD Video Decoder,0x005fffff,2,4,msmpeg2vdec.dll,10.00.19041.0928
AC3 Parser Filter,0x00600000,1,1,mpg2splt.ax,10.00.19041.0329
StreamBufferSink,0x00200000,0,0,sbe.dll,10.00.19041.0001
MJPEG Decompressor,0x00600000,1,1,quartz.dll,10.00.19041.0746
MPEG-I Stream Splitter,0x00600000,1,2,quartz.dll,10.00.19041.0746
SAMI (CC) Parser,0x00400000,1,1,quartz.dll,10.00.19041.0746
VBI Codec,0x00600000,1,4,VBICodec.ax,10.00.19041.0746
MPEG-2 Splitter,0x005fffff,1,0,mpg2splt.ax,10.00.19041.0329
Closed Captions Analysis Filter,0x00200000,2,5,cca.dll,10.00.19041.0001
SBE2FileScan,0x00200000,0,0,sbe.dll,10.00.19041.0001
Microsoft MPEG-2 Video Encoder,0x00200000,1,1,msmpeg2enc.dll,10.00.19041.0001
Internal Script Command Renderer,0x00800001,1,0,quartz.dll,10.00.19041.0746
MPEG Audio Decoder,0x03680001,1,1,quartz.dll,10.00.19041.0746
DV Splitter,0x00600000,1,2,qdv.dll,10.00.19041.0001
Video Mixing Renderer 9,0x00200000,1,0,quartz.dll,10.00.19041.0746
Microsoft MPEG-2 Encoder,0x00200000,2,1,msmpeg2enc.dll,10.00.19041.0001
ACM Wrapper,0x00600000,1,1,quartz.dll,10.00.19041.0746
Video Renderer,0x00800001,1,0,quartz.dll,10.00.19041.0746
MPEG-2 Video Stream Analyzer,0x00200000,0,0,sbe.dll,10.00.19041.0001
Line 21 Decoder,0x00600000,1,1,,
Video Port Manager,0x00600000,2,1,quartz.dll,10.00.19041.0746
Video Renderer,0x00400000,1,0,quartz.dll,10.00.19041.0746
VPS Decoder,0x00200000,0,0,WSTPager.ax,10.00.19041.0001
WM ASF Writer,0x00400000,0,0,qasf.dll,12.00.19041.0001
VBI Surface Allocator,0x00600000,1,1,vbisurf.ax,

File writer,0x00200000,1,0,qcap.dll,10.00.19041.0001
DVD Navigator,0x00200000,0,3,qdvd.dll,10.00.19041.0746
Overlay Mixer2,0x00200000,1,1,,
AVI Draw,0x00600064,9,1,quartz.dll,10.00.19041.0746
Microsoft MPEG-2 Audio Encoder,0x00200000,1,1,msmpeg2enc.dll,10.00.19041.0001
WST Pager,0x00200000,1,1,WSTPager.ax,10.00.19041.0001
MPEG-2 Demultiplexer,0x00600000,1,1,mpg2splt.ax,10.00.19041.0329
DV Video Decoder,0x00800000,1,1,qdv.dll,10.00.19041.0001
SampleGrabber,0x00200000,1,1,qedit.dll,10.00.19041.0746
Null Renderer,0x00200000,1,0,qedit.dll,10.00.19041.0746
MPEG-2 Sections and Tables,0x005fffff,1,0,Mpeg2Data.ax,10.00.19041.0001
Microsoft AC3 Encoder,0x00200000,1,1,msac3enc.dll,10.00.19041.0001
StreamBufferSource,0x00200000,0,0,sbe.dll,10.00.19041.0001
Smart Tee,0x00200000,1,2,qcap.dll,10.00.19041.0001
Overlay Mixer,0x00200000,0,0,,
AVI Decompressor,0x00600000,1,1,quartz.dll,10.00.19041.0746
AVI/WAV File Source,0x00400000,0,2,quartz.dll,10.00.19041.0746
Wave Parser,0x00400000,1,1,quartz.dll,10.00.19041.0746
MIDI Parser,0x00400000,1,1,quartz.dll,10.00.19041.0746
Multi-file Parser,0x00400000,1,1,quartz.dll,10.00.19041.0746
File stream renderer,0x00400000,1,1,quartz.dll,10.00.19041.0746
Microsoft DTV-DVD Audio Decoder,0x005fffff,1,1,msmpeg2adec.dll,10.00.19041.0001
StreamBufferSink2,0x00200000,0,0,sbe.dll,10.00.19041.0001
AVI Mux,0x00200000,1,0,qcap.dll,10.00.19041.0001
Line 21 Decoder 2,0x00600002,1,1,quartz.dll,10.00.19041.0746
File Source (Async.),0x00400000,0,1,quartz.dll,10.00.19041.0746
File Source (URL),0x00400000,0,1,quartz.dll,10.00.19041.0746
Infinite Pin Tee Filter,0x00200000,1,1,qcap.dll,10.00.19041.0001
Enhanced Video Renderer,0x00200000,1,0,evr.dll,10.00.19041.0546
BDA MPEG2 Transport Information Filter,0x00200000,2,0,psisrndr.ax,10.00.19041.0001
MPEG Video Decoder,0x40000001,1,1,quartz.dll,10.00.19041.0746

WDM Streaming Tee/Splitter Devices:
Tee/Sink-to-Sink-Konvertierung,0x00200000,1,1,ksproxy.ax,10.00.19041.0746

Video Compressors:
WMVideo8 Encoder DMO,0x00600800,1,1,wmvxencd.dll,10.00.19041.0867
WMVideo9 Encoder DMO,0x00600800,1,1,wmvencod.dll,10.00.19041.0001
MSScreen 9 encoder DMO,0x00600800,1,1,wmvsencd.dll,10.00.19041.0001
DV Video Encoder,0x00200000,0,0,qdv.dll,10.00.19041.0001
MJPEG Compressor,0x00200000,0,0,quartz.dll,10.00.19041.0746

Audio Compressors:
WM Speech Encoder DMO,0x00600800,1,1,WMSPDMOE.DLL,10.00.19041.0508
WMAudio Encoder DMO,0x00600800,1,1,WMADMOE.DLL,10.00.19041.0508
IMA ADPCM,0x00200000,1,1,quartz.dll,10.00.19041.0746
PCM,0x00200000,1,1,quartz.dll,10.00.19041.0746
Microsoft ADPCM,0x00200000,1,1,quartz.dll,10.00.19041.0746
GSM 6.10,0x00200000,1,1,quartz.dll,10.00.19041.0746
CCITT A-Law,0x00200000,1,1,quartz.dll,10.00.19041.0746
CCITT u-Law,0x00200000,1,1,quartz.dll,10.00.19041.0746
MPEG Layer-3,0x00200000,1,1,quartz.dll,10.00.19041.0746

Audio Capture Sources:
Microphone Array (Realtek(R) Audio),0x00200000,0,0,qcap.dll,10.00.19041.0001

PBDA CP Filters:
PBDA DTFilter,0x00600000,1,1,CPFilters.dll,10.00.19041.0746
PBDA ETFilter,0x00200000,0,0,CPFilters.dll,10.00.19041.0746
PBDA PTFilter,0x00200000,0,0,CPFilters.dll,10.00.19041.0746

Midi Renderers:
Default MidiOut Device,0x00800000,1,0,quartz.dll,10.00.19041.0746
Microsoft GS Wavetable Synth,0x00200000,1,0,quartz.dll,10.00.19041.0746

WDM Streaming Capture Devices:
,0x00000000,0,0,,
HP Webcam,0x00200000,1,1,ksproxy.ax,10.00.19041.0746
,0x00000000,0,0,,
Realtek HD Audio Mic input with SST,0x00200000,1,3,ksproxy.ax,10.00.19041.0746
,0x00000000,0,0,,
Mic in at front panel (black),0x00200000,1,1,ksproxy.ax,10.00.19041.0746
,0x00000000,0,0,,
,0x00000000,0,0,,
,0x00200000,1,1,,

WDM Streaming Rendering Devices:
,0x00000000,0,0,,
Realtek HD Audio 2nd output with SST,0x00200000,2,2,ksproxy.ax,10.00.19041.0746
Realtek HD Audio output with SST,0x00200000,2,2,ksproxy.ax,10.00.19041.0746
,0x00200000,1,1,,
,0x00200000,1,1,,
,0x00000000,0,0,,
Intel(R) Display-Audio - Ausgang 2.1,0x00200000,1,1,ksproxy.ax,10.00.19041.0746
,0x00200000,1,1,,
,0x00000000,0,0,,

BDA Network Providers:
Microsoft ATSC Network Provider,0x00200000,0,1,MSDvbNP.ax,10.00.19041.0001
Microsoft DVBC Network Provider,0x00200000,0,1,MSDvbNP.ax,10.00.19041.0001
Microsoft DVBS Network Provider,0x00200000,0,1,MSDvbNP.ax,10.00.19041.0001
Microsoft DVBT Network Provider,0x00200000,0,1,MSDvbNP.ax,10.00.19041.0001
Microsoft Network Provider,0x00200000,0,1,MSNP.ax,10.00.19041.0001

Video Capture Sources:
HP Webcam,0x00200000,1,1,ksproxy.ax,10.00.19041.0746

Multi-Instance Capable VBI Codecs:
VBI Codec,0x00600000,1,4,VBICodec.ax,10.00.19041.0746

BDA Transport Information Renderers:
BDA MPEG2 Transport Information Filter,0x00600000,2,0,psisrndr.ax,10.00.19041.0001
MPEG-2 Sections and Tables,0x00600000,1,0,Mpeg2Data.ax,10.00.19041.0001

WDM Streaming Communication Transforms:
Tee/Sink-to-Sink-Konvertierung,0x00200000,1,1,ksproxy.ax,10.00.19041.0746

Audio Renderers:
LG PROJECTOR (Intel(R) Display-Audio),0x00200000,1,0,quartz.dll,10.00.19041.0746
Default DirectSound Device,0x00800000,1,0,quartz.dll,10.00.19041.0746
Default WaveOut Device,0x00200000,1,0,quartz.dll,10.00.19041.0746
DirectSound: LG PROJECTOR (Intel(R) Display-Audio),0x00200000,1,0,quartz.dll,10.00.19041.0746
DirectSound: HP Speaker (Realtek(R) Audio),0x00200000,1,0,quartz.dll,10.00.19041.0746
HP Speaker (Realtek(R) Audio),0x00200000,1,0,quartz.dll,10.00.19041.0746

Preferred DirectShow Filters

[HKEY_LOCAL_MACHINE\Software\Microsoft\DirectShow\Preferred]

<media subtype GUID>, [<filter friendly name>,]<filter CLSID>

MEDIASUBTYPE_DVD_LPCM_AUDIO, Microsoft DTV-DVD Audio Decoder, CLSID_CMPEG2AudDecoderDS
MEDIASUBTYPE_MPEG2_AUDIO, Microsoft DTV-DVD Audio Decoder, CLSID_CMPEG2AudDecoderDS
MEDIASUBTYPE_MPEG2_VIDEO, Microsoft DTV-DVD Video Decoder, CLSID_CMPEG2VidDecoderDS
{78766964-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject
{7634706D-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject
MEDIASUBTYPE_mp4s, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject
{64697678-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject
{58564944-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject
{5634504D-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject
MEDIASUBTYPE_MP4S, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject
MEDIASUBTYPE_WMVR, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject
MEDIASUBTYPE_WMVP, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject
{44495658-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject
MEDIASUBTYPE_WMVA, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject
MEDIASUBTYPE_mpg4, Mpeg4 Decoder DMO, CLSID_CMpeg4DecMediaObject
MEDIASUBTYPE_MPG4, Mpeg4 Decoder DMO, CLSID_CMpeg4DecMediaObject
MEDIASUBTYPE_h264, Microsoft DTV-DVD Video Decoder, CLSID_CMPEG2VidDecoderDS
MEDIASUBTYPE_H264, Microsoft DTV-DVD Video Decoder, CLSID_CMPEG2VidDecoderDS
MEDIASUBTYPE_WMV3, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject
MEDIASUBTYPE_mp43, Mpeg43 Decoder DMO, CLSID_CMpeg43DecMediaObject
MEDIASUBTYPE_MP43, Mpeg43 Decoder DMO, CLSID_CMpeg43DecMediaObject
MEDIASUBTYPE_m4s2, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject

MEDIASUBTYPE_WMV2, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject
MEDIASUBTYPE_MSS2, WMV Screen decoder DMO, CLSID_CMSSCDecMediaObject
MEDIASUBTYPE_M4S2, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject
MEDIASUBTYPE_WVP2, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject
MEDIASUBTYPE_mp42, Mpeg4 Decoder DMO, CLSID_CMpeg4DecMediaObject
MEDIASUBTYPE_MP42, Mpeg4 Decoder DMO, CLSID_CMpeg4DecMediaObject
MEDIASUBTYPE_WMV1, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject
MEDIASUBTYPE_MSS1, WMV Screen decoder DMO, CLSID_CMSSCDecMediaObject
MEDIASUBTYPE_WVC1, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject
MEDIASUBTYPE_AVC1, Microsoft DTV-DVD Video Decoder, CLSID_CMPEG2VidDecoderDS
MEDIASUBTYPE_MPEG_LOAS, Microsoft DTV-DVD Audio Decoder,
CLSID_CMPEG2AudDecoderDS
MEDIASUBTYPE_MPEG_ADTS_AAC, Microsoft DTV-DVD Audio Decoder,
CLSID_CMPEG2AudDecoderDS
MEDIASUBTYPE_WMAUDIO_LOSSLESS, WMAudio Decoder DMO,
CLSID_CWMADecMediaObject
MEDIASUBTYPE_WMAUDIO3, WMAudio Decoder DMO, CLSID_CWMADecMediaObject
WMMEDIASUBTYPE_WMAudioV8, WMAudio Decoder DMO,
CLSID_CWMADecMediaObject
MEDIASUBTYPE_MSAUDIO1, WMAudio Decoder DMO, CLSID_CWMADecMediaObject
MEDIASUBTYPE_RAW_AAC1, Microsoft DTV-DVD Audio Decoder,
CLSID_CMPEG2AudDecoderDS
WMMEDIASUBTYPE_MP3, MP3 Decoder DMO, CLSID_CMP3DecMediaObject
MEDIASUBTYPE_MPEG1Payload, MPEG Video Decoder, CLSID_CMpegVideoCodec
MEDIASUBTYPE_MPEG1Packet, MPEG Video Decoder, CLSID_CMpegVideoCodec
{6C737664-0000-0010-8000-00AA00389B71}, DV Video Decoder, CLSID_DVVideoCodec
{64737664-0000-0010-8000-00AA00389B71}, DV Video Decoder, CLSID_DVVideoCodec
{64687664-0000-0010-8000-00AA00389B71}, DV Video Decoder, CLSID_DVVideoCodec
MEDIASUBTYPE_MJPG, MJPEG Decompressor, CLSID_MjpegDec
{20637664-0000-0010-8000-00AA00389B71}, DV Video Decoder, CLSID_DVVideoCodec
MEDIASUBTYPE_MPEG1AudioPayload, MPEG Audio Decoder, CLSID_CMpegAudioCodec
WMMEDIASUBTYPE_WMSP2, WMSpeech Decoder DMO, CLSID_CWMSPDecMediaObject
WMMEDIASUBTYPE_WMSP1, WMSpeech Decoder DMO, CLSID_CWMSPDecMediaObject

---
Media Foundation File Versions
---

mfcore.dll, 10.00.19041.0928
mfreadwrite.dll, 10.00.19041.0746
mfcaptureengine.dll, 10.00.19041.0906
mfsensorgroup.dll, 10.00.19041.0906
windows.media.dll, 10.00.19041.0906
frameserver.dll, 10.00.19041.0906
frameserverclient.dll, 10.00.19041.0906

Media Foundation Transforms

[HKEY_LOCAL_MACHINE\Software\Classes\MediaFoundation\Transforms]

<category>:
  <transform friendly name>, <transform CLSID>, <flags>, [<merit>,]<file name>, <file version>

Video Decoders:
  Intel® Hardware M-JPEG Decoder MFT, {00C69F81-0524-48C0-A353-4DD9D54F9A6E}, 0x6, 7, mfx_mft_mjpgvd_64.dll, 10.20.0009.0015
  NVIDIA MJPEG Video Decoder MFT, {70F36578-2741-454F-B494-E8563DDD1CB4}, 0x4, 8, nvDecMFTMjpegx.dll, 27.21.0014.5763
  Intel® Hardware M-JPEG Decoder MFT, {00C69F81-0524-48C0-A353-4DD9D54F9A6E}, 0x6, 7, mfx_mft_mjpgvd_64.dll, 10.20.0009.0015
  Microsoft MPEG Video Decoder MFT, {2D709E52-123F-49B5-9CBC-9AF5CDE28FB9}, 0x1, msmpeg2vdec.dll, 10.00.19041.0928
  DV Decoder MFT, {404A6DE5-D4D6-4260-9BC7-5A6CBD882432}, 0x1, mfdvdec.dll, 10.00.19041.0001
  Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT, 0x1, mp4sdecd.dll, 10.00.19041.0450
  Microsoft H264 Video Decoder MFT, CLSID_CMSH264DecoderMFT, 0x1, msmpeg2vdec.dll, 10.00.19041.0928
  WMV Screen decoder MFT, CLSID_CMSSCDecMediaObject, 0x1, wmvsdecd.dll, 10.00.19041.0001
  WMVideo Decoder MFT, CLSID_CWMVDecMediaObject, 0x1, wmvdecod.dll, 10.00.19041.0928
  MJPEG Decoder MFT, {CB17E772-E1CC-4633-8450-5617AF577905}, 0x1, mfmjpegdec.dll, 10.00.19041.0329
  Mpeg43 Decoder MFT, CLSID_CMpeg43DecMediaObject, 0x1, mp43decd.dll, 10.00.19041.0001
  Mpeg4 Decoder MFT, CLSID_CMpeg4DecMediaObject, 0x1, mpg4decd.dll, 10.00.19041.0001
  HEIFImageExtension
  VP9VideoExtensionDecoder
  WebpImageExtension
Video Encoders:
  Intel® Quick Sync Video H.264 Encoder MFT, {4BE8D3C0-0515-4A37-AD55-E4BAE19AF471}, 0x4, 7, mfx_mft_h264ve_64.dll, 10.20.0009.0015
  Intel® Hardware H265 Encoder MFT, {BC10864D-2B34-408F-912A-102B1B867B6C}, 0x4, 7, mfx_mft_h265ve_64.dll, 10.20.0009.0015
  Intel® Hardware VP9 Encoder MFT, {D186A626-77CA-4D80-942F-61E0A5111AFE}, 0x4, 7, mfx_mft_vp9ve_64.dll, 10.20.0009.0015
  Intel® Quick Sync Video H.264 Encoder MFT, {4BE8D3C0-0515-4A37-AD55-E4BAE19AF471}, 0x4, 7, mfx_mft_h264ve_64.dll, 10.20.0009.0015
  Intel® Hardware H265 Encoder MFT, {BC10864D-2B34-408F-912A-102B1B867B6C}, 0x4, 7, mfx_mft_h265ve_64.dll, 10.20.0009.0015
  Intel® Hardware VP9 Encoder MFT, {D186A626-77CA-4D80-942F-61E0A5111AFE}, 0x4, 7, mfx_mft_vp9ve_64.dll, 10.20.0009.0015
  H264 Encoder MFT, {6CA50344-051A-4DED-9779-A43305165E35}, 0x1, mfh264enc.dll, 10.00.19041.0001
  WMVideo8 Encoder MFT, CLSID_CWMVXEncMediaObject, 0x1, wmvxencd.dll, 10.00.19041.0867
  H263 Encoder MFT, {BC47FCFE-98A0-4F27-BB07-698AF24F2B38}, 0x1, mfh263enc.dll, 10.00.19041.0001
  WMVideo9 Encoder MFT, CLSID_CWMV9EncMediaObject, 0x1, wmvencod.dll, 10.00.19041.0001

Microsoft MPEG-2 Video Encoder MFT, {E6335F02-80B7-4DC4-ADFA-DFE7210D20D5}, 0x2, msmpeg2enc.dll, 10.00.19041.0001
HEIFImageExtension
VP9VideoExtensionEncoder
Video Effects:
Frame Rate Converter, CLSID_CFrameRateConvertDmo, 0x1, mfvdsp.dll, 10.00.19041.0746
Resizer MFT, CLSID_CResizerDMO, 0x1, vidreszr.dll, 10.00.19041.0867
VideoStabilization MFT, {51571744-7FE4-4FF2-A498-2DC34FF74F1B}, 0x1, MSVideoDSP.dll, 10.00.19041.0746
Color Control, CLSID_CColorControlDmo, 0x1, mfvdsp.dll, 10.00.19041.0746
Color Converter MFT, CLSID_CColorConvertDMO, 0x1, colorcnv.dll, 10.00.19041.0867
Video Processor:
Microsoft Video Processor MFT, {88753B26-5B24-49BD-B2E7-0C445C78C982}, 0x1, msvproc.dll, 10.00.19041.0789
Audio Decoders:
Microsoft Dolby Digital Plus Decoder MFT, {177C0AFE-900B-48D4-9E4C-57ADD250B3D4}, 0x1, DolbyDecMFT.dll, 10.00.19041.0928
MS AMRNB Decoder MFT, {265011AE-5481-4F77-A295-ABB6FFE8D63E}, 0x1, MSAMRNBDecoder.dll, 10.00.19041.0001
WMAudio Decoder MFT, CLSID_CWMADecMediaObject, 0x1, WMADMOD.DLL, 10.00.19041.0508
Microsoft AAC Audio Decoder MFT, CLSID_CMSAACDecMFT, 0x1, MSAudDecMFT.dll, 10.00.19041.0867
A-law Wrapper MFT, {36CB6E0C-78C1-42B2-9943-846262F31786}, 0x1, mfcore.dll, 10.00.19041.0928
GSM ACM Wrapper MFT, {4A76B469-7B66-4DD4-BA2D-DDF244C766DC}, 0x1, mfcore.dll, 10.00.19041.0928
WMAPro over S/PDIF MFT, CLSID_CWMAudioSpdTxDMO, 0x1, WMADMOD.DLL, 10.00.19041.0508
Microsoft Opus Audio Decoder MFT, {63E17C10-2D43-4C42-8FE3-8D8B63E46A6A}, 0x1, MSOpusDecoder.dll, 10.00.19041.0746
Microsoft FLAC Audio Decoder MFT, {6B0B3E6B-A2C5-4514-8055-AFE8A95242D9}, 0x1, MSFlacDecoder.dll, 10.00.19041.0746
Microsoft MPEG Audio Decoder MFT, {70707B39-B2CA-4015-ABEA-F8447D22D88B}, 0x1, MSAudDecMFT.dll, 10.00.19041.0867
WMSpeech Decoder DMO, CLSID_CWMSPDecMediaObject, 0x1, WMSPDMOD.DLL, 10.00.19041.0001
G711 Wrapper MFT, {92B66080-5E2D-449E-90C4-C41F268E5514}, 0x1, mfcore.dll, 10.00.19041.0928
IMA ADPCM ACM Wrapper MFT, {A16E1BFF-A80D-48AD-AECD-A35C005685FE}, 0x1, mfcore.dll, 10.00.19041.0928
MP3 Decoder MFT, CLSID_CMP3DecMediaObject, 0x1, mp3dmod.dll, 10.00.19041.0001
Microsoft ALAC Audio Decoder MFT, {C0CD7D12-31FC-4BBC-B363-7322EE3E1879}, 0x1, MSAlacDecoder.dll, 10.00.19041.0746
ADPCM ACM Wrapper MFT, {CA34FE0A-5722-43AD-AF23-05F7650257DD}, 0x1, mfcore.dll, 10.00.19041.0928
Dolby TrueHD IEC-61937 converter MFT, {CF5EEEDF-0E92-4B3B-A161-BD0FFE545E4B}, 0x1, mfaudiocnv.dll, 10.00.19041.0746
DTS IEC-61937 converter MFT, {D035E24C-C877-42D7-A795-2A8A339B472F}, 0x1, mfaudiocnv.dll, 10.00.19041.0746
DTSXDecoder
DTSHDDecoder

Audio Encoders:
  LPCM DVD-Audio MFT, {068A8476-9229-4CC0-9D49-2FC699DCD30A}, 0x1, mfaudiocnv.dll, 10.00.19041.0746
  MP3 Encoder ACM Wrapper MFT, {11103421-354C-4CCA-A7A3-1AFF9A5B6701}, 0x1, mfcore.dll, 10.00.19041.0928
  Microsoft FLAC Audio Encoder MFT, {128509E9-C44E-45DC-95E9-C255B8F466A6}, 0x1, MSFlacEncoder.dll, 10.00.19041.0746
  WM Speech Encoder DMO, CLSID_CWMSPEncMediaObject2, 0x1, WMSPDMOE.DLL, 10.00.19041.0508
  MS AMRNB Encoder MFT, {2FAE8AFE-04A3-423A-A814-85DB454712B0}, 0x1, MSAMRNBEncoder.dll, 10.00.19041.0001
  Microsoft MPEG-2 Audio Encoder MFT, {46A4DD5C-73F8-4304-94DF-308F760974F4}, 0x1, msmpeg2enc.dll, 10.00.19041.0001
  WMAudio Encoder MFT, CLSID_CWMAEncMediaObject, 0x1, WMADMOE.DLL, 10.00.19041.0508
  Microsoft AAC Audio Encoder MFT, {93AF0C51-2275-45D2-A35B-F2BA21CAED00}, 0x1, mfAACEnc.dll, 10.00.19041.0001
  Microsoft ALAC Audio Encoder MFT, {9AB6A28C-748E-4B6A-BFFF-CC443B8E8FB4}, 0x1, MSAlacEncoder.dll, 10.00.19041.0746
  Microsoft Dolby Digital Encoder MFT, {AC3315C9-F481-45D7-826C-0B406C1F64B8}, 0x1, msac3enc.dll, 10.00.19041.0001
  DTS Headphone:X
  DTS:X Ultra
  DTS:X for home theater
Audio Effects:
  AEC, CLSID_CWMAudioAEC, 0x1, mfwmaaec.dll, 10.00.19041.0001
  Resampler MFT, CLSID_CResamplerMediaObject, 0x1, resampledmo.dll, 10.00.19041.0001
Multiplexers:
  Microsoft MPEG2 Multiplexer MFT, {AB300F71-01AB-46D2-AB6C-64906CB03258}, 0x2, mfmpeg2srcsnk.dll, 10.00.19041.0870
Others:
  Microsoft H264 Video Remux (MPEG2TSToMP4) MFT, {05A47EBB-8BF0-4CBF-AD2F-3B71D75866F5}, 0x1, msmpeg2vdec.dll, 10.00.19041.0928

Media Foundation Enabled Hardware Categories

[HKEY_LOCAL_MACHINE\Software\Microsoft\Windows Media Foundation\HardwareMFT]

EnableEncoders = 1
EnableDecoders = 1

Media Foundation Byte Stream Handlers

[HKEY_LOCAL_MACHINE\Software\Microsoft\Windows Media Foundation\ByteStreamHandlers]
[HKEY_LOCAL_MACHINE\Software\Classes\MediaFoundation\MediaSources\Preferred]

<file ext. or MIME type>, <handler CLSID>, <brief description>[, Preferred]

.3g2, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
.3gp, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
.3gp2, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
.3gpp, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
.aac, {926F41F7-003E-4382-9E84-9E953BE10562}, ADTS Byte Stream Handler, Preferred
.ac3, {46031BA1-083F-47D9-8369-23C92BDAB2FF}, AC-3 Byte Stream Handler, Preferred
.adt, {926F41F7-003E-4382-9E84-9E953BE10562}, ADTS Byte Stream Handler, Preferred
.adts, {926F41F7-003E-4382-9E84-9E953BE10562}, ADTS Byte Stream Handler, Preferred
.am?, {EFE6208A-0A2C-49FA-8A01-3768B559B6DA}, MF AMRNB Media Source ByteStreamHandler
.amr, {EFE6208A-0A2C-49FA-8A01-3768B559B6DA}, MF AMRNB Media Source ByteStreamHandler, Preferred
.asf, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred
.avi, {7AFA253E-F823-42F6-A5D9-714BDE467412}, AVI Byte Stream Handler, Preferred
.dvr-ms, {A8721937-E2FB-4D7A-A9EE-4EB08C890B6E}, MF SBE Source ByteStreamHandler
.dvr-ms, {65964407-A5D8-4060-85B0-1CCD63F768E2}, dvr-ms Byte Stream Handler, Preferred
.ec3, {46031BA1-083F-47D9-8369-23C92BDAB2FF}, AC-3 Byte Stream Handler, Preferred
.flac, {0E41CFB8-0506-40F4-A516-77CC23642D91}, MF FLAC Media Source ByteStreamHandler, Preferred
.m2t, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.m2ts, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.m4a, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
.m4v, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
.mk3d, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, MKV Byte Stream Handler, Preferred
.mka, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, MKV Byte Stream Handler, Preferred
.mks, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, MKV Byte Stream Handler, Preferred
.mkv, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, MKV Byte Stream Handler, Preferred
.mod, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.mov, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
.mp2v, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.mp3, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred
.mp4, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
.mp4v, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
.mpa, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred
.mpeg, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.mpg, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.mts, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.nsc, {B084785C-DDE0-4D30-8CA8-05A373E185BE}, NSC Byte Stream Handler, Preferred
.sami, {7A56C4CB-D678-4188-85A8-BA2EF68FA10D}, SAMI Byte Stream Handler, Preferred
.smi, {7A56C4CB-D678-4188-85A8-BA2EF68FA10D}, SAMI Byte Stream Handler, Preferred
.tod, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.ts, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.tts, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.uvu, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
.vob, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.wav, {42C9B9F5-16FC-47EF-AF22-DA05F7C842E3}, WAV Byte Stream Handler, Preferred
.weba, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, WEBM Byte Stream Handler, Preferred
.webm, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, WEBM Byte Stream Handler, Preferred
.wm, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred

.wma, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred
.wmv, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred
.wtv, {65964407-A5D8-4060-85B0-1CCD63F768E2}, WTV Byte Stream Handler, Preferred
audio/3gpp, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
audio/3gpp2, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
audio/aac, {926F41F7-003E-4382-9E84-9E953BE10562}, ADTS Byte Stream Handler, Preferred
audio/aacp, {926F41F7-003E-4382-9E84-9E953BE10562}, ADTS Byte Stream Handler, Preferred
audio/eac3, {46031BA1-083F-47D9-8369-23C92BDAB2FF}, AC-3 Byte Stream Handler, Preferred
audio/flac, {0E41CFB8-0506-40F4-A516-77CC23642D91}, MF FLAC Media Source ByteStreamHandler, Preferred
audio/L16, {3FFB3B8C-EB99-472B-8902-E1C1B05F07CF}, LPCM Byte Stream Handler, Preferred
audio/mp3, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred
audio/mp4, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
audio/MP4A-LATM, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
audio/mpa, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred
audio/mpeg, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred
audio/mpeg3, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred
audio/vnd.dlna.adts, {926F41F7-003E-4382-9E84-9E953BE10562}, ADTS Byte Stream Handler, Preferred
audio/vnd.dolby.dd-raw, {46031BA1-083F-47D9-8369-23C92BDAB2FF}, AC-3 Byte Stream Handler, Preferred
audio/wav, {42C9B9F5-16FC-47EF-AF22-DA05F7C842E3}, WAV Byte Stream Handler, Preferred
audio/webm, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, WEBM Byte Stream Handler, Preferred
audio/x-aac, {926F41F7-003E-4382-9E84-9E953BE10562}, ADTS Byte Stream Handler, Preferred
audio/x-flac, {0E41CFB8-0506-40F4-A516-77CC23642D91}, MF FLAC Media Source ByteStreamHandler, Preferred
audio/x-m4a, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
audio/x-matroska, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, MKV Byte Stream Handler, Preferred
audio/x-mp3, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred
audio/x-mpeg, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred
audio/x-ms-wma, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred
audio/x-wav, {42C9B9F5-16FC-47EF-AF22-DA05F7C842E3}, WAV Byte Stream Handler, Preferred
video/3gpp, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
video/3gpp2, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred

video/avi, {7AFA253E-F823-42F6-A5D9-714BDE467412}, AVI Byte Stream Handler, Preferred
video/mp4, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
video/mpeg, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
video/msvideo, {7AFA253E-F823-42F6-A5D9-714BDE467412}, AVI Byte Stream Handler, Preferred
video/vnd.dece.mp4, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
video/vnd.dlna.mpeg-tts, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
video/webm, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, WEBM Byte Stream Handler, Preferred
video/x-m4v, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
video/x-matroska, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, MKV Byte Stream Handler, Preferred
video/x-ms-asf, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred
video/x-ms-wm, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred
video/x-ms-wmv, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred
video/x-msvideo, {7AFA253E-F823-42F6-A5D9-714BDE467412}, AVI Byte Stream Handler, Preferred

---
Media Foundation Scheme Handlers

[HKEY_LOCAL_MACHINE\Software\Microsoft\Windows Media Foundation\SchemeHandlers]
[HKEY_LOCAL_MACHINE\Software\Classes\MediaFoundation\MediaSources\Preferred]

<URL type>, <handler CLSID>, <brief description>[, Preferred]

file:, {477EC299-1421-4BDD-971F-7CCB933F21AD}, File Scheme Handler, Preferred
http:, {44CB442B-9DA9-49DF-B3FD-023777B16E50}, Http Scheme Handler
http:, {9EC4B4F9-3029-45AD-947B-344DE2A249E2}, Urlmon Scheme Handler
http:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred
httpd:, {44CB442B-9DA9-49DF-B3FD-023777B16E50}, Http Scheme Handler, Preferred
https:, {37A61C8B-7F8E-4D08-B12B-248D73E9AB4F}, Secure Http Scheme Handler, Preferred
httpsd:, {37A61C8B-7F8E-4D08-B12B-248D73E9AB4F}, Secure Http Scheme Handler, Preferred
httpt:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred
httpu:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred
mcast:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred
mcrecv:, {FA6D33D4-9405-4BA5-9983-12604AC8E77A}, Miracast Sink Scheme Handler, Preferred
mms:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred
ms-appdata:, {CFC81939-3886-4ACF-9692-DA58037AE716}, MsAppData Scheme Handler, Preferred

ms-appx-web:, {8DB0224B-3D65-4F6F-8E12-BEB4B78B8974}, MsAppxWeb Scheme Handler, Preferred
ms-appx:, {8DB0224B-3D65-4F6F-8E12-BEB4B78B8974}, MsAppx Scheme Handler, Preferred
ms-winsoundevent:, {F79A6BF9-7415-4CF3-AE10-4559509ABC3C}, Sound Event Scheme Handler, Preferred
rtsp:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred
rtsps:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred
rtspt:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred
rtspu:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred
sdp:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred

---
Preferred Media Foundation Transforms

[HKEY_LOCAL_MACHINE\Software\Classes\MediaFoundation\Transforms\Preferred]

<media subtype GUID>, [<transform friendly name>,]<transform CLSID>

{EB27CEC4-163E-4CA3-8B74-8E25F91B517E}, Dolby TrueHD IEC-61937 converter MFT, {CF5EEEDF-0E92-4B3B-A161-BD0FFE545E4B}
{E06D802C-DB46-11CF-B4D1-00805F6CBBEA}, Microsoft Dolby Digital Plus Decoder MFT, {177C0AFE-900B-48D4-9E4C-57ADD250B3D4}
MFVideoFormat_MPEG2, Microsoft MPEG Video Decoder MFT, {2D709E52-123F-49B5-9CBC-9AF5CDE28FB9}
MEDIASUBTYPE_DOLBY_DDPLUS, Microsoft Dolby Digital Plus Decoder MFT, {177C0AFE-900B-48D4-9E4C-57ADD250B3D4}
{A61AC364-AD0E-4744-89FF-213CE0DF8804}, DTS IEC-61937 converter MFT, {D035E24C-C877-42D7-A795-2A8A339B472F}
{A2E58EB7-0FA9-48BB-A40C-FA0E156D0645}, DTS IEC-61937 converter MFT, {D035E24C-C877-42D7-A795-2A8A339B472F}
{7634706D-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT
{73616D72-767A-494D-B478-F29D25DC9037}, MS AMRNB Decoder MFT, {265011AE-5481-4F77-A295-ABB6FFE8D63E}
MEDIASUBTYPE_mp4s, Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT
MFVideoFormat_DVSL, DV Decoder MFT, {404A6DE5-D4D6-4260-9BC7-5A6CBD882432}
MFVideoFormat_DVSD, DV Decoder MFT, {404A6DE5-D4D6-4260-9BC7-5A6CBD882432}
MFVideoFormat_DVHD, DV Decoder MFT, {404A6DE5-D4D6-4260-9BC7-5A6CBD882432}
{63616C61-0000-0010-8000-00AA00389B71}, Microsoft ALAC Audio Decoder MFT, {C0CD7D12-31FC-4BBC-B363-7322EE3E1879}
MFVideoFormat_MP4V, Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT
MFVideoFormat_MP4S, Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT
{53314356-0000-0010-8000-00AA00389B71}, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject
MEDIASUBTYPE_WMVR, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject
MEDIASUBTYPE_WMVP, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject
MFVideoFormat_MJPG, MJPEG Decoder MFT, {CB17E772-E1CC-4633-8450-5617AF577905}
MEDIASUBTYPE_WMVA, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject
{3F40F4F0-5622-4FF8-B6D8-A17A584BEE5E}, Microsoft H264 Video Decoder MFT, CLSID_CMSH264DecoderMFT

MEDIASUBTYPE_mpg4, Mpeg4 Decoder MFT, CLSID_CMpeg4DecMediaObject
MEDIASUBTYPE_MPG4, Mpeg4 Decoder MFT, CLSID_CMpeg4DecMediaObject
MFVideoFormat_H264, Microsoft H264 Video Decoder MFT, CLSID_CMSH264DecoderMFT
MFVideoFormat_WMV3, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject
{33363248-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT
MEDIASUBTYPE_mp43, Mpeg43 Decoder MFT, CLSID_CMpeg43DecMediaObject
MFVideoFormat_MP43, Mpeg43 Decoder MFT, CLSID_CMpeg43DecMediaObject
MEDIASUBTYPE_m4s2, Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT
MFVideoFormat_WMV2, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject
MFVideoFormat_MSS2, WMV Screen decoder MFT, CLSID_CMSSCDecMediaObject
MFVideoFormat_M4S2, Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT
MEDIASUBTYPE_WVP2, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject
MEDIASUBTYPE_mp42, Mpeg4 Decoder MFT, CLSID_CMpeg4DecMediaObject
MEDIASUBTYPE_MP42, Mpeg4 Decoder MFT, CLSID_CMpeg4DecMediaObject
MFVideoFormat_WMV1, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject
MFVideoFormat_MSS1, WMV Screen decoder MFT, CLSID_CMSSCDecMediaObject
MFVideoFormat_MPG1, Microsoft MPEG Video Decoder MFT, {2D709E52-123F-49B5-9CBC-9AF5CDE28FB9}
MFVideoFormat_WVC1, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject
MFVideoFormat_DVC, DV Decoder MFT, {404A6DE5-D4D6-4260-9BC7-5A6CBD882432}
{0000F1AC-0000-0010-8000-00AA00389B71}, Microsoft FLAC Audio Decoder MFT, {6B0B3E6B-A2C5-4514-8055-AFE8A95242D9}
{00007361-0000-0010-8000-00AA00389B71}, MS AMRNB Decoder MFT, {265011AE-5481-4F77-A295-ABB6FFE8D63E}
{0000704F-0000-0010-8000-00AA00389B71}, Microsoft Opus Audio Decoder MFT, {63E17C10-2D43-4C42-8FE3-8D8B63E46A6A}
{00006C61-0000-0010-8000-00AA00389B71}, Microsoft ALAC Audio Decoder MFT, {C0CD7D12-31FC-4BBC-B363-7322EE3E1879}
{00002001-0000-0010-8000-00AA00389B71}, DTS IEC-61937 converter MFT, {D035E24C-C877-42D7-A795-2A8A339B472F}
{00002000-0000-0010-8000-00AA00389B71}, Microsoft Dolby Digital Plus Decoder MFT, {177C0AFE-900B-48D4-9E4C-57ADD250B3D4}
MFAudioFormat_AAC, Microsoft AAC Audio Decoder MFT, CLSID_CMSAACDecMFT
MFAudioFormat_ADTS, Microsoft AAC Audio Decoder MFT, CLSID_CMSAACDecMFT
MFAudioFormat_WMAudio_Lossless, WMAudio Decoder MFT, CLSID_CWMADecMediaObject
MFAudioFormat_WMAudioV9, WMAudio Decoder MFT, CLSID_CWMADecMediaObject
MFAudioFormat_WMAudioV8, WMAudio Decoder MFT, CLSID_CWMADecMediaObject
MEDIASUBTYPE_MSAUDIO1, WMAudio Decoder MFT, CLSID_CWMADecMediaObject
MEDIASUBTYPE_RAW_AAC1, Microsoft AAC Audio Decoder MFT, CLSID_CMSAACDecMFT
MFAudioFormat_MP3, MP3 Decoder MFT, CLSID_CMP3DecMediaObject
MFAudioFormat_MPEG, Microsoft MPEG Audio Decoder MFT, {70707B39-B2CA-4015-ABEA-F8447D22D88B}
{00000031-0000-0010-8000-00AA00389B71}, GSM ACM Wrapper MFT, {4A76B469-7B66-4DD4-BA2D-DDF244C766DC}
{00000011-0000-0010-8000-00AA00389B71}, IMA ADPCM ACM Wrapper MFT, {A16E1BFF-A80D-48AD-AECD-A35C005685FE}
KSDATAFORMAT_SUBTYPE_MULAW, G711 Wrapper MFT, {92B66080-5E2D-449E-90C4-C41F268E5514}
{00000006-0000-0010-8000-00AA00389B71}, A-law Wrapper MFT, {36CB6E0C-78C1-42B2-9943-846262F31786}

KSDATAFORMAT_SUBTYPE_ADPCM, ADPCM ACM Wrapper MFT, {CA34FE0A-5722-43AD-AF23-05F7650257DD}
WMMEDIASUBTYPE_WMSP2, WMSpeech Decoder DMO, CLSID_CWMSPDecMediaObject
MFAudioFormat_MSP1, WMSpeech Decoder DMO, CLSID_CWMSPDecMediaObject

---
Disabled Media Foundation Transforms

[HKEY_LOCAL_MACHINE\Software\Classes\MediaFoundation\Transforms\DoNotUse]

<transform CLSID>

Disabled Media Sources

[HKEY_LOCAL_MACHINE\Software\Classes\MediaFoundation\MediaSources\DoNotUse]

<media source CLSID>

EVR Power Information

Current Setting: {5C67A112-A4C9-483F-B4A7-1D473BECAFDC} (Quality)
  Quality Flags: 2576
    Enabled:
    Force throttling
    Allow half deinterlace
    Allow scaling
    Decode Power Usage: 100
  Balanced Flags: 1424
    Enabled:
    Force throttling
    Allow batching
    Force half deinterlace
    Force scaling
    Decode Power Usage: 50
  PowerFlags: 1424
    Enabled:
    Force throttling
    Allow batching
    Force half deinterlace
    Force scaling
    Decode Power Usage: 0

Diagnostics

Windows Error Reporting:
+++ WER0 +++:
Bucket errato 1436932331615254398, tipo 4
Nome evento: APPCRASH
Risposta: Non disponibile
ID CAB: 0

Firma problema:
P1: Cities.exe
P2: 5.6.7.3267
P3: 5c73fc7c
P4: StackHash_2264
P5: 0.0.0.0
P6: 00000000
P7: c0000005
P8: PCH_FA_FROM_unknown+0x0000000000000000
P9:
P10:

File allegati:
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER4A2A.tmp.mdmp
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER4C0F.tmp.WERInternalMetadata.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER4C30.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER4C2E.tmp.csv
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER4C5E.tmp.txt

I file potrebbero essere disponibili qui:
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportArchive\
AppCrash_Cities.exe_248560e1978c257d5ad312a66151906a75a1140_ea05ca7c_82d78dfa-1614-45bd-aa2c-e9a2a1a2f9a1

Simbolo analisi:
Nuova ricerca di soluzioni: 0
ID rapporto: d8e7bdfa-17d5-4dea-90a9-45a27bddf1d3
Stato rapporto: 268435456
Bucket con hash: 1934dd8b3a550796f3f10257a833777e
GUID CAB: 0
+++ WER1 +++:
Bucket errato 2089864828596311100, tipo 5
Nome evento: AppHangB1
Risposta: Nicht verfügbar
ID CAB: 0

Firma problema:
P1: Cities.exe
P2: 5.6.7.3267
P3: 5c73fc7c
P4: 6950
P5: 67508224
P6:

P7:
P8:
P9:
P10:

File allegati:
\\?\C:\Users\luigi\AppData\Local\Temp\WER6F49.tmp.version.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER6F59.tmp.WERInternalMetadata.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER6F7A.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER6F78.tmp.csv
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER6F98.tmp.txt
\\?\C:\Users\luigi\AppData\Local\Temp\WER6FAA.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportQueue\
Critical_Cities.exe_3f97aa542746bd2680f8c4a856a725f92ebbd_ea05ca7c_cab_77d45c9b-74d1-4b06-aec0-2c0648e8540a\minidump.mdmp
WERGenerationLog.txt

I file potrebbero essere disponibili qui:
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportArchive\
Critical_Cities.exe_3f97aa542746bd2680f8c4a856a725f92ebbd_ea05ca7c_77d45c9b-74d1-4b06-aec0-2c0648e8540a

Simbolo analisi:
Nuova ricerca di soluzioni: 0
ID rapporto: f71911e4-ccfa-4d7b-9d69-8828cc4f6e5a
Stato rapporto: 268435456
Bucket con hash: 38e4251958e54aa8ed00b0fd3110d43c
GUID CAB: 0
+++ WER2 +++:
Bucket errato , tipo 0
Nome evento: AppHangB1
Risposta: Non disponibile
ID CAB: 0

Firma problema:
P1: Cities.exe
P2: 5.6.7.3267
P3: 5c73fc7c
P4: 6950
P5: 67508224
P6:
P7:
P8:
P9:
P10:

File allegati:
\\?\C:\Users\luigi\AppData\Local\Temp\WER6F49.tmp.version.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER6F59.tmp.WERInternalMetadata.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER6F7A.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER6F78.tmp.csv
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER6F98.tmp.txt

\\?\C:\Users\luigi\AppData\Local\Temp\WER6FAA.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportQueue\
Critical_Cities.exe_3f97aa542746bd2680f8c4a856a725f92ebbd_ea05ca7c_cab_77d45c9b-74d1-4b06-aec0-2c0648e8540a\minidump.mdmp
WERGenerationLog.txt

I file potrebbero essere disponibili qui:
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportQueue\
Critical_Cities.exe_3f97aa542746bd2680f8c4a856a725f92ebbd_ea05ca7c_cab_77d45c9b-74d1-4b06-aec0-2c0648e8540a

Simbolo analisi:
Nuova ricerca di soluzioni: 0
ID rapporto: f71911e4-ccfa-4d7b-9d69-8828cc4f6e5a
Stato rapporto: 4
Bucket con hash:
GUID CAB: 0
+++ WER3 +++:
Bucket errato 2089864828596311100, tipo 5
Nome evento: AppHangB1
Risposta: Nicht verfügbar
ID CAB: 0

Firma problema:
P1: Cities.exe
P2: 5.6.7.3267
P3: 5c73fc7c
P4: 6950
P5: 67508224
P6:
P7:
P8:
P9:
P10:

File allegati:
\\?\C:\Users\luigi\AppData\Local\Temp\WEREA21.tmp.version.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WEREA41.tmp.WERInternalMetadata.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WEREA61.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WEREA6F.tmp.csv
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WEREA9F.tmp.txt
\\?\C:\Users\luigi\AppData\Local\Temp\WEREAA1.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportQueue\
Critical_Cities.exe_3f97aa542746bd2680f8c4a856a725f92ebbd_ea05ca7c_cab_a22920b3-9bf3-40f2-a604-a8142b004fce\minidump.mdmp
WERGenerationLog.txt

I file potrebbero essere disponibili qui:
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportArchive\
Critical_Cities.exe_3f97aa542746bd2680f8c4a856a725f92ebbd_ea05ca7c_a22920b3-9bf3-40f2-a604-a8142b004fce

Simbolo analisi:
Nuova ricerca di soluzioni: 0
ID rapporto: c13f2cd6-654e-4c17-8f3d-3c9b4e1793bb
Stato rapporto: 268435456
Bucket con hash: 38e4251958e54aa8ed00b0fd3110d43c
GUID CAB: 0
+++ WER4 +++:
Bucket errato , tipo 0
Nome evento: AppHangB1
Risposta: Non disponibile
ID CAB: 0

Firma problema:
P1: Cities.exe
P2: 5.6.7.3267
P3: 5c73fc7c
P4: 6950
P5: 67508224
P6:
P7:
P8:
P9:
P10:

File allegati:
\\?\C:\Users\luigi\AppData\Local\Temp\WEREA21.tmp.version.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WEREA41.tmp.WERInternalMetadata.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WEREA61.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WEREA6F.tmp.csv
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WEREA9F.tmp.txt
\\?\C:\Users\luigi\AppData\Local\Temp\WEREAA1.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportQueue\
Critical_Cities.exe_3f97aa542746bd2680f8c4a856a725f92ebbd_ea05ca7c_cab_a22920b3-9bf3-40f2-a604-a8142b004fce\minidump.mdmp
WERGenerationLog.txt

I file potrebbero essere disponibili qui:
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportQueue\
Critical_Cities.exe_3f97aa542746bd2680f8c4a856a725f92ebbd_ea05ca7c_cab_a22920b3-9bf3-40f2-a604-a8142b004fce

Simbolo analisi:
Nuova ricerca di soluzioni: 0
ID rapporto: c13f2cd6-654e-4c17-8f3d-3c9b4e1793bb
Stato rapporto: 4
Bucket con hash:
GUID CAB: 0
+++ WER5 +++:
Bucket errato 0x113_19_nvlddmkm!NvDispatchPower, tipo 0
Nome evento: BlueScreen
Risposta: Nicht verfügbar
ID CAB: 9ad36c63-9fe4-459e-8795-cc96d723c5de

Firma problema:
P1: 113
P2: 19
P3: 2
P4: 10de
P5: 1d16
P6: 10_0_19042
P7: 0_0
P8: 768_1
P9:
P10:

File allegati:
\\?\C:\windows\Minidump\041621-11781-01.dmp
\\?\C:\windows\TEMP\WER-24062-0.sysdata.xml
\\?\C:\windows\MEMORY.DMP
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERA20C.tmp.WERInternalMetadata.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERA21D.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERA25A.tmp.csv
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERA28A.tmp.txt

I file potrebbero essere disponibili qui:
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportArchive\
Kernel_113_08665066519a48bbf1f2a1f1b8bfa83548f07c_00000000_cab_ec6e764f-a82d-4b44-92fb-36f3a9527a90

Simbolo analisi:
Nuova ricerca di soluzioni: 0
ID rapporto: 71223c6b-4bf1-4957-aa0f-7536df1633b8
Stato rapporto: 268435456
Bucket con hash:
GUID CAB: 0
+++ WER6 +++:
Bucket errato , tipo 0
Nome evento: BlueScreen
Risposta: Nicht verfügbar
ID CAB: 0

Firma problema:
P1: 113
P2: 19
P3: 2
P4: 10de
P5: 1d16
P6: 10_0_19042
P7: 0_0
P8: 768_1
P9:
P10:

File allegati:

\\?\C:\windows\Minidump\041621-11781-01.dmp
\\?\C:\windows\TEMP\WER-24062-0.sysdata.xml
\\?\C:\windows\MEMORY.DMP
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERA20C.tmp.WERInternalMetadata.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERA21D.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERA25A.tmp.csv
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERA28A.tmp.txt

I file potrebbero essere disponibili qui:
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportQueue\
Kernel_113_08665066519a48bbf1f2a1f1b8bfa83548f07c_00000000_cab_ec6e764f-a82d-4b44-92fb-36f3a9527a90

Simbolo analisi:
Nuova ricerca di soluzioni: 0
ID rapporto: 71223c6b-4bf1-4957-aa0f-7536df1633b8
Stato rapporto: 4
Bucket con hash:
GUID CAB: 0
+++ WER7 +++:
Bucket errato 2089864828596311100, tipo 5
Nome evento: AppHangB1
Risposta: Nicht verfügbar
ID CAB: 0

Firma problema:
P1: Cities.exe
P2: 5.6.7.3267
P3: 5c73fc7c
P4: 6950
P5: 67508224
P6:
P7:
P8:
P9:
P10:

File allegati:
\\?\C:\Users\luigi\AppData\Local\Temp\WERF011.tmp.version.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERF032.tmp.WERInternalMetadata.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERF042.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERF050.tmp.csv
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERF070.tmp.txt
\\?\C:\Users\luigi\AppData\Local\Temp\WERF072.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportQueue\
Critical_Cities.exe_3f97aa542746bd2680f8c4a856a725f92ebbd_ea05ca7c_cab_95556bfd-b5a9-4edc-b393-b9684471ccf5\minidump.mdmp
WERGenerationLog.txt

I file potrebbero essere disponibili qui:

\\?\C:\ProgramData\Microsoft\Windows\WER\ReportArchive\
Critical_Cities.exe_3f97aa542746bd2680f8c4a856a725f92ebbd_ea05ca7c_95556bfd-b5a9-4edc-b393-b9684471ccf5

Simbolo analisi:
Nuova ricerca di soluzioni: 0
ID rapporto: 9fcde0fa-84f4-48a1-8e72-822c8a219f07
Stato rapporto: 268435456
Bucket con hash: 38e4251958e54aa8ed00b0fd3110d43c
GUID CAB: 0
+++ WER8 +++:
Bucket errato , tipo 0
Nome evento: AppHangB1
Risposta: Non disponibile
ID CAB: 0

Firma problema:
P1: Cities.exe
P2: 5.6.7.3267
P3: 5c73fc7c
P4: 6950
P5: 67508224
P6:
P7:
P8:
P9:
P10:

File allegati:
\\?\C:\Users\luigi\AppData\Local\Temp\WERF011.tmp.version.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERF032.tmp.WERInternalMetadata.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERF042.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERF050.tmp.csv
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERF070.tmp.txt
\\?\C:\Users\luigi\AppData\Local\Temp\WERF072.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportQueue\
Critical_Cities.exe_3f97aa542746bd2680f8c4a856a725f92ebbd_ea05ca7c_cab_95556bfd-b5a9-4edc-b393-b9684471ccf5\minidump.mdmp
WERGenerationLog.txt

I file potrebbero essere disponibili qui:
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportQueue\
Critical_Cities.exe_3f97aa542746bd2680f8c4a856a725f92ebbd_ea05ca7c_cab_95556bfd-b5a9-4edc-b393-b9684471ccf5

Simbolo analisi:
Nuova ricerca di soluzioni: 0
ID rapporto: 9fcde0fa-84f4-48a1-8e72-822c8a219f07
Stato rapporto: 4
Bucket con hash:
GUID CAB: 0
+++ WER9 +++:

Bucket errato 2089864828596311100, tipo 5
Nome evento: AppHangB1
Risposta: Nicht verfügbar
ID CAB: 0

Firma problema:
P1: Cities.exe
P2: 5.6.7.3267
P3: 5c73fc7c
P4: 6950
P5: 67508224
P6:
P7:
P8:
P9:
P10:

File allegati:
\\?\C:\Users\luigi\AppData\Local\Temp\WER189F.tmp.version.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER18B0.tmp.WERInternalMetadata.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER18D0.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER18CE.tmp.csv
\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER18FE.tmp.txt
\\?\C:\Users\luigi\AppData\Local\Temp\WER1900.tmp.xml
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportQueue\
Critical_Cities.exe_3f97aa542746bd2680f8c4a856a725f92ebbd_ea05ca7c_cab_c3fc87ab-79f9-4596-82f9-c45636526dda\minidump.mdmp
WERGenerationLog.txt

I file potrebbero essere disponibili qui:
\\?\C:\ProgramData\Microsoft\Windows\WER\ReportArchive\
Critical_Cities.exe_3f97aa542746bd2680f8c4a856a725f92ebbd_ea05ca7c_c3fc87ab-79f9-4596-82f9-c45636526dda

Simbolo analisi:
Nuova ricerca di soluzioni: 0
ID rapporto: 3b2f078e-ca66-497a-8ffa-dbca15e29cda
Stato rapporto: 268435456
Bucket con hash: 38e4251958e54aa8ed00b0fd3110d43c
GUID CAB: 0